



GOVERNMENT OF INDIA
MINISTRY OF MINES
INDIAN BUREAU OF MINES
OFFICE OF THE REGIONAL CONTROLLER OF MINES

Violation letter
By Email/Post



File No.: MP/JBP/Lat-16

Jabalpur, Dated: 03/01/2023

To,

Shri Vinod Kumar Shrivastav, Owner
Main Road Gandhigram, Tehsil-Sihora
District- Jabalpur (M.P.) 483222
Email- vksmines@gmail.com , shrivastav558@gmail.com

Sub.: Violation of provisions of Mineral Conservation and Development Rules, 2017, in respect to Kurro Manganese and Laterite mine over an extent of 7.30 hectare Mine Code 75MPR18015 in District Jabalpur of Madhya Pradesh State.

Sir,

The following provision of Mineral Conservation and Development Rules 2017 were found violated in your above mentioned mine during the inspection by the undersigned on 21/12/2022 in presence of QP Shri R.K Chowbey.

Rule No	Nature of violation observed in detail
Rule 11(1)	<p><i>No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub-section (2) of section 5.</i></p> <ol style="list-style-type: none">1. Only 26065 Tonnes of Manganese was produced against the proposed production of 30242 Tonnes during 2021-2022.2. Bench width of about 3 meters is observed; against to maintain more than 6 meters (Bench height), thus benches are not systematically developed as proposed.3. Pit No.02, Waste Dump-WD-3 and Waste dump-WD-4 are found extended beyond the lease boundary on Eastern side and Waste dump-WD-5 and Stack-1 encroached the lease boundary on the southern side of the lease. Thus Mining operations are found carried out encroaching safety barrier of 7.5 meters of lease boundary without having any such approved proposals.
Rule 12(4)	<p><i>In the case of existing mining leases detailed exploration (G1 level) over the entire potentially mineralised area under the mining lease shall be carried out within a period of five years from the date of commencement of these rules.</i></p> <p>It is observed that only 5.50 ha area out of 7.30ha was explored in G1 which is 75% of the total area the rest 25% was in G2 level.</p>
Rule 26(2)	<p><i>The holder of mining lease shall submit to the competent authority a yearly report as per the format specified by the Indian Bureau of Mines, before 1st day of July every year setting forth the extent of protective and rehabilitative works carried out as envisaged in the approved mine closure plan, and if there is any deviation,</i></p>

	During inspection & scrutiny of the office records, it was observed that the a yearly report setting forth the extent of protective and rehabilitative works carried out as envisaged in the approved mine closure plan, has not been submitted so for to the Regional Controller of Mines, IBM Jabalpur.
Rule 31(4)	<i>The plans and sections required under these rules shall be maintained up to date within three months in case of category 'A' mines as referred to in clause (a) of sub-rule (2) of rule 55, and within twelve months in the case of any other mine</i> The updated plans and sections are not matching with actual field conditions.
Rule 37(2)	<i>The dumps shall be properly secured to prevent escape of material there from in harmful quantities which may cause degradation of environment and to prevent causation of floods.</i> Garland drains and retaining walls are not being properly maintained around the periphery of existing dumps.

2. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017.
3. Non compliance of rule 11(1) of MCDR, 2017 may lead to suspension of mining operation under the provision of rule 11(2) of MCDR-2017.
3. You are advised to rectify the above violations immediately and intimate the position to this office within a period of 45 days from the date of issue of this letter.

Yours faithfully

K.N. Gaur
03/01/2023

(Kathroju Naveen)

Sr. Asst. Controller of Mines,
Jabalpur Region, IBM

Copy to:

1. The Director of Geology & Mining, Government of Madhya Pradesh, Khanij Bhavan, Arera Hills, Bhopal (MP). (All Lease Boundary Pillars not found established to delineate the lease area on the field).
2. The District Collector, Jabalpur

K.N. Gaur
03/01/2023

(Kathroju Naveen)

Sr. Asst. Controller of Mines,
Jabalpur Region,
IBM

1. खान नियंत्रक, भारतीय खान ब्यूरो, नागपुर को सोचानार्थ प्रेषित

K.N. Gaur
03/01/2023

(कथोरोजू नावीन)

वारिसता सहायक खान नियंत्रक