

Government of India
Ministry of Mines
Indian Bureau of Mines
Office of the Regional Controller of Mines, Jabalpur

File No.: MP/SATNA/LST-120

Jabalpur, Dated: 08.07.2022

To,

Shri N K Verma (Nominated Owner),
Near NH-7, Rewa Road,
Vill:- Amilia, Lakhwar Maihar,
Tehsil:- Maihar, Distt:- Satna M.P., Pin -485771

Sub. : Violation of provisions of Mineral Conservation and Development Rules, 2017, in respect of your **Piprahat Limestone Mine** (7.316 hectare) Mine Code **38MPR35062** in District Satna of M.P. State.

Sir,

Following provisions of MCDR 2017 were found violated in your above mine during the inspection by the Undersigned on **06/04/2022** in the presence of Shri K.P. Nigam (AVP Mines), Shri. Rakesh Choubey (Qualified person) & mines officials:

Rule No	Nature of violation observed in detail
11(1)	No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government. <ul style="list-style-type: none">As per proposal, the garland drain and bund along with settling tank to be maintained in the boundary side and around the dump to prevent siltation of low-lying areas and in rush of water into the mine. But it was observed during inspection that no garland drain and bund along with settling tank have been constructed in the boundary area and around the dump and the mine pit was submerged in water on the day of inspection.The boundary pillars were not erected as per rule.
34 A (3)	Every lessee shall carry out a drone survey of his leased area and upto hundred metres outside the lease boundary within six months before submission of any mining plan document or modification thereto to the Indian Bureau of Mines for approval and shall submit processed output [digital elevation model (DEM) and Orthomosaic] images obtained from such survey or any other format as may be specified by the Indian Bureau of Mines in this regard to the concerned Regional Controller of Mines and the Controller General along with the application for approval of mining plan: (DEM) and Orthomosaic images obtained from drone survey was not submitted during the application of the mining plan.

- In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017.
- The mining operations can be suspended under the rule 11(2) of MCDR-2017, if compliance of rule 11(1) of MCDR-2017 is not found satisfactory.
- You are advised to rectify the violations of abovementioned rules immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

Yours faithfully


(Robert Simon C)

Asst. Controller of Mines,
Jabalpur Region, IBM