

MCDR-MiFLOLST/9/2023-HYD-IBM_RO_HYD Hkkir lidki@government of India

[kku ea=ky;@ministry of mines

Hkkjrh; [kku C;wjks@indian bureau of mines {ks=h; [kku fu;a=d dk;kZy;@office of the regional

CONTROLLER OF MINES

k uacj 603] NBok; ry] IhOthOvksO VkWolZ]@Room No. 603, 6th Floor, CGO Towers, 成MhxqMk] fidanikckn ¼rsyaxkuk½&500080@Kavadiguda, Secundrabad, (Telangana) - 500080

Qksu@Phone% 040&29555603] 29554603] 29553603] bZ&esy@E-mail%

ro.hyderabad@ibm.gov.in

File No. AP/KSN/LST-26/Hyd

38APR10027

To

Nominated Owner/Agent, Muktyala Limestone mine M/s KCP Cements Ltd,

Ramakrishna Buildings No.2,

Dr. P.V.Cherian Crescent, Egmore, Chennai – 600008

Tamil Nadu

Sub:

Violation of provisions of MCDR, 2017 in respect of Muktyala Limestone Mine over an area of 368.35 ha. in Muktyala Village of Jaggayyapeta Mandal of District Krishna, State Andhra Pradesh

Sir/Madam,

The following provisions of Mineral Conservation and Development Rules, 2017 (as amended up to 2021) were found violated in the above mine during the inspection on 20/07/2023 by the undersigned in presence of the mine officials Shri B. Anil Kumar. Mines Manager

Rule No.	Proposed in the approved mining	Violation
	plan / Rule	
11 (1)	As per the approved Review of mining plan dated 14.12.2021 i) It is proposed to produce 4500037 t quantity of limestone mineral during the year 2022-23 by operating pit-1 between grid location E399988-E400888, N1862643-N1863193 & pit-2 between grid location E401188-E401300, N1862443-N1862643.	i) During inspection it is observed that the production of limestone quantity is 2986700 t (with deviation of 34%) for the year 2022-23 and pits were operated pit-1 between grid location E400138-E400888, N1862643-N1863193& pit-2 between grid location E401138-E401300, N1862523-N1862643 which is deviation from the approved mining plan proposal.

- 02. In this connection, it is brought to your notice that the violation of aforesaid rule constitutes an offence punishable under Rule 62(1) of MCDR, 2017.
- 03. The mining operations can also be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
- 04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

Yours faithfully,

Violation Letter / mYya?

Date: 27/07/2023

(Ramkishan R) Deputy Controller of Mines Indian Bureau of Mines l/13930/2023 **d`0i`0i0**

---2--

&2&

izfrfyfi% lwpukFkZ ,oa vko';d dk;Zokgh gsrq %&

- 1-[kku fu;a=d ¼nf{k.k½] Hkkjrh; [kku C;wjks] caxywj ¼dukZVd½ & 560022
- **2.** The Director of Mines and Geology, Government of Andhra Pradesh, Sri Anjaneya Towers, Door No.7-104, B-Block, 5th and 6th Floors, BTPS Road, PO Ibrahimpatnam-521456, Vijayawada, Krishna District.
- 3.The Agent, Muktyala Limestone Mine M/s KCP Cements Limited, Muktyala (Village), Jaggayapeta (Mandal), NTR (District), A.P. 521457

(Ramkishan R)
Deputy Controller of Mines drs $\{ks=h; [kkufu; a=d/For Regional Controller of Mines]\}$