MCDR-MiFLOLST/19/2023-BNG-IBM_RO_BNG INDIAN BUREAU OF MINES

MINERALS DEVELOPMENT AND REGULATION DIVISION

Review and updation of Mining Plan REPORT

Bangalore regional office

Mine file No : KNT/CTD/LST/20/BNG Mine code : 38KAR07009

(i) Name of the Inspecting: 277) GANGADHAR BHAKAT

Officer and ID No.

(ii) Designation : Assistant Mining Engineer

(iii) Accompaning mine : Muralibabu.B.K - Prdn. Manager

Official with Designation

1/29266/2024

(iv) Date of Inspection : 21/12/2023

(v) Prev.inspection date :

PART-I : GENERAL INFORMATION

.. (a) Mine Name : LAXMI (S.NO.1861)

(b) Registration NO. : IBM/5988/2011

(c) Category : A Fully Mechanised

 $\text{(d)} \qquad \text{Type of Working} \qquad \qquad : \quad \text{Opencast} \\$

(e) Postal address

State : KARNATAKA

District : CHITRADURGA

Village : ITTIGEHALLI

Taluka : HOSADURGA

Post office : Pin Code :

FAX No. : 080-223562148

E-mail : vanimine@gmail.com

Phone : 080-23562153, 9448531929 (mc

(f) Police Station : HOSADURGA

(g) First opening date :

(h) Weekly day of rest : SUN

2. Address for : LAKSHMI CEMENT&CERAMICS INDUSTRIES LTD

correspondance FLAT NO. 302, R.V. APARTMENTS, PIPELINE ROAD

11TH CROSS, MALLESWARAM, BENGALURU 577 503

3. (a) Lease Number : KAR1098 ML No 2472

(b) Lease area : 20.23 Ha

(c) Period of lease : 50 Years, up to 17/01/2033
 (d) Date of Expiry : 17/01/2023 17/01/2033

4. Mineral worked : LIMESTONE Main

DOLOMITE Associated

PAGE : 2

1/29266/2024

5. Name and Address of the

Lessee : LAKSHMI CEMENT&CERAMICS INDUSTRIES LTD

#5,SERPENTINE ROAD, 8 TH BLOCK, KUMARAPARK(WEST), BANGALORE KARNATAKA

Phone: 080-3312666, 3441504, 08199-82234

FAX :

Owner : Pavankumar Medishetty

MJ Nagar #2278/1 28th cross Hosapete vijaynagara-563201

BELLARY KARNATAKA

Phone: FAX:

Mining Engineer

Name : ISHAIAH K, Full Time

Qualification : B-Tech (Min) Appointment/ : 16/11/2021

Termination date

Geologist

Name : MOHAN KUMAR S, Full Time

Qualification : MSc Geology

Appointment/ : Termination date

Manager

Name : B K MURALIBABU

Qualification : Appointment/ : Termination date

6. Date of approval of Mining : Existing rule 11 MCDR1988 15/12/1998 Plan/Scheme of Mining Renewal under rule 22 MCR1960 05/12/2003 Modif.of approved Mining Plan 08/09/2006

Modif.of approved Mining Plan 08/09/2006 Mining Scheme rule 12 MCDR1988 15/01/2009 MP modif under 17(3) MCR 2016 12/04/2018

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
1a	Backlog of previous year	15 Core Borehole up to 750m.	NIL	No exploration carried out against the proposal for the year 2018-19 & 2019-20. Violation pointed out.
1b	Exploration over lease area for geological axis 1 or 2		NIL	
1c	Exploration Agencies and Expenditure in lakh rupees during the year		NA	
1d	Balance area to be explored to bring Geological axis in 1 or 2		G3- 12.83Ha	
1e	Balance reserve as on 01/04/20		4775011 Tones as on 01.04.2023	CaO 35.48% to 52.05%
1f	General remarks of inspecting officers on geology, exploration etc			There is no exploration carried out against the proposal of 15 Core Borehole up to 750m for the year 2018-19 & 2019-20. Violation pointed out.

Development :

Sl.No.	Item	Propasals	Actual work	Remarks
2a	Location of development w.r.t.lease area	Between section line 5-5' to 6-6'	Between section line 5-5' to 6-6'	-
2b	Separate benches in topsoil, overburden and minerals (Rule 15)		Carried out as per proposal.	
2c	Stripping ratio or ore to OB ratio	1:0.03	1:0.28	Ore: 49495 Tones OB: 13800 Tones, Violation pointed out.

2d	Quantity of topsoil generation in m3	No proposal.	NIL	-
2e	Quantity of overburden generation in m3	80000m3	6900 m3	Violation pointed out.
2f	General remarks of inspecting officers on development of pit w.r.t. type of deposit etc			Only 9% of proposed production and development carried out during the year 2022-23. Hence, violation pointed out.

Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
3a	Number of pit proposed for production	One pit proposed.	One pit.	-
3b	Quantity of ROM mineral production proposed	600000 Tons	49495 Tons	Violation pointed out.
3с	Recovery of sailable/usable mineral from ROM production	100%	100%	-
3d	Quantity of mineral reject generation	No proposal.	Nil.	No mineral reject generation.
3e	Grade of mineral rejects generation and threshold value declared.	No proposal.	Nil.	THV CaO 34%
3f	Quantity of sub grade mineral generation.	No proposal.	NIL	
3g	Grade of sub grade mineral generation	No proposal.	NIL	
3h	Manual / Mechanised method adopted for segregating from ROM	Mechanized method proposed for sizing of ROM.	Carried out as per proposal.	

3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.	No proposal.	NIL	
3ј	Provision of drilling and blasting in mineral benches	Drilling & Blasting proposed in mineral benches.	Carried out as proposed.	
3k	Provision of mining machineries in mineral benches	Proposal of i) Excavator -3 Nos. ii) Loader- 2 Nos. iii) Dumper- 10 Nos. iv) Wagon Drill- 1 No, v) Rock Breaker-1 No, vi) Water tanker-5 KL-1 No, vii) Crusher- 1No.	i)Excavator -2 Nos. ii)Loader- 1 Nos. iii) Dumper- 4 Nos. iv) Crusher- 1No.	
31	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	Proposal for Bench height up to 6m.	Bench height maintained up to 6m.	
3 m	Total area covered under excavation/pits	6.09 Ha.	3.09На.	During the plan period mine was reopened on 17/11/2021.
3n	Ore to OB ratio for the pit/mine during the year.	1:0.26 (in tons)	1:0.27 (in tons)	Ore: 49495 Tons OB: 13800Tons
30	Total area put in use under different heads at the end of year	i)Area under Mining- 6.09 Ha, ii)Waste dump-2.50 Ha, iii) Roads - 0.50 Ha, iv)Others- 11.14Ha	i)Area under Mining-3.09 Ha, ii)Waste dump- 1.69 Ha, iii)Infrastructure- 1.3 Ha.	During the plan period mine was reopened on 17/11/2021.

3p	Production of ROM mineral during the last five year period as applicable	2018-19: Nil. 2019-20:Nil. 2020-21:Nil. 2021-22:Nil. 2022-23: 49495 (in Tones)	
3q	General remarks of inspecting officers on method of mining etc.		Only 9% of proposed production and development carried out during the year 2022-23. Hence, violation pointed out.

Solid Waste Management - Dumping:

Sl.No.	Item	Propasals	Actual work	Remarks
4a	Separate dumping of topsoil, OB and mineral rejects (Rule 32,33)	Separate dumping of OB proposed.	Carried out as per proposal.	No mineral Reject generation.
4b	Location of topsoil, OB and mineral reject dumps	OB proposed: N1526700 to 1526900, E660552 to 660850	OB dumping carried at the proposed location as per the proposal.	-
4c	Number of dumps within lease area and outside of lease area	WML-1 OML-0	WML-5 OML-0	
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	4 Dumps are within UPL & 1 Dump outside the UPL.	4 Dumps are within UPL & 1 Dump outside the UPL.	
4e	Number of active and alive dumps.	1 Active dump.	1 Active dump.	
4f	Number of dead dumps.	4 Inactive dumps.	4 Inactive dumps.	One inactive dump outside the UPL.
4g	Number of dumps established.	No proposal.	1 Inactive dump.	1 Inactive dump stabilized by plantation.

4h 4i	Whether Retaining wall or garland drain all along dumps are there. Length of		NIL	-
	Retaining wall or garland drain all along dumps			
4j	Number of settling ponds	No proposal.	NIL	-
4k	Specific comments of inspecting officer on waste dump management			The OB dumping has been carried out at the earmarked location as per proposal.

Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	No proposal.	Nil.	Mineral has not been exhausted.
5b	Area under backfilling of mined out area	No proposal.	NA	
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	No proposal.	NIL	No topsoil generated during the year 2022-23.
5d	Total area fully reclaimed and rehabilitated	No proposal.	NIL	-
5e 	General remarks of inspecting officers on backfilling and reclamation etc.			There is no backfilling proposal during the plan period.
	Progressive Mine (Clousre Plan:		
Sl.No.	Item	Propasals	Actual work	Remarks

6a	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	To be submitted before 1st of July every year.	Not submitted.	Violation pointed out.
6b	Area available for rehabilitation (ha) .	No proposal.	NIL	
6c	afforestation done (ha).	0.20 Ha	0.20 Ha	
6d	No. of saplings planted during the year	Saplings to be planted 200 No's	250 No's. of saplings planted.	As per AR for the FY 2022-23.
6e	Cumulative no .of plants	WML 1000 Nos	WML 650 No's	WML total 650 No's of plantation carried out during the plan period.
6f	Any other method of rehabilitation	No proposal.	NIL	
6g	Cost incurred on watch and care during the year	Rs 10000/-	Rs 60000/-	Information furnished by mine management during the inspection.
6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling (Lx B x D	No proposal.	NIL	
6i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	No proposal.	NIL	
6j	Compliance on reclamation and rehabilitation by backfilling (iii) Afforestati on on backfilled area	No proposal.	NIL	

6k	Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir	No proposal.	NIL	
61	Compliance on reclamation and rehabilitation by backfilling (v) any other specific means.	No proposal.	NIL	
6m	Compliance of rehabilitation of waste land within lease (i)afforestation	No proposal.	250 No's	Total 250 No's of saplings planted within the safety zone as per proposal.
6n	Compliance of rehabilitation of waste land within lease (ii) Area rehabilitation (ha)	No proposal.	NIL	
60	Compliance of rehabilitation of waste land within lease (iii) Method of rehabilitation	No proposal.	NIL	
6p	Compliance of environmental monitoring (core zone and buffer zone)	Seasons wise environmental monitoring of air, water, soil & noise proposed for both core & buffer zone.	Season wise environmental monitoring of air, water, soil & noise was carried out by M/s Care Lab, Hyderabad.	All environment monitoring parameters are within the permissible limits.
6q 	General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.			Total 250 No's of saplings planted within the safety zone as per proposal.

Actual work

Remarks

Mineral Conservation:

Item

Propasals

Sl.No.

7a	ROM Mineral dispatch or grade-wise sorting within lease area	ROM mineral only crushing & sizing proposed.	Blasted material is being sent to the crusher for further sizing.	
7b	Method of grade- wise mineral sorting i.e. manual or mechanical.	Mechanical method proposed for size-wise sorting of mineral.	Carried out as per proposal.	
7c	Different grade of mineral sorted out at mines.	No proposal.	NIL	
7d	Any beneficiation process at mines	No proposal.	NIL	
7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues			Entire ROM produced is being used for dispatched with proper blending as per buyer requirement.

Environment:

Sl.No.	Item	Propasals	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	No proposal.	Nil.	No topsoil generation.
8b	Concurrent use or storage of topsoil	No proposal.	NIL	
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	Separate dump proposed for overburden.	Dumping carried out as per proposal in the earmarked location	
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	No proposal.	NIL	

8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	No proposal.	NIL	
8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	WML 1000 Nos	WML 650 No's	WML total 650 No's of plantation carried out during the plan period.
8g	Survival rate	80%	85%	
8h	Water sprinkling on roads to control airborne dust	sprinkling on	Water sprinkling on haul roads carried out for dust suppression.	Capacity of water tanker 10000 Ltr.
8i	General remarks of inspecting officer on aesthetic beauty in and around mines area			The aesthetic beauty in and around the mine is good.

Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual	work		Remarks
9a	Status of submission of Monthly and Annual returns	MR Submitted up to November 2023. AR Submitted up to 2022-23.				MR Submitted on 06/12/2023. AR Submitted on 30/06/2023.
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	Mining Engineer- Ishaiah K & Geologist - Mohankumar .S	Appear	to be	correct.	-
9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	Mining-3.09 Ha, ii)Waste dump- 1.69 Ha, iii)Infrastruc	Appear	to be	correct.	-

9d	Scrutiny of Annual return on afforestation		Appear to be correct.	-
9e	Scrutiny of Annual return on mineral reject generation (Grade and quantity)	NIL	Appear to be correct.	-
9f	Scrutiny of Annual return on ROM stock and/or graded ore	- /	The ROM closing stock has not been reported correctly.	Violation pointed out under rule 45(7) of MCDR 2017.
9g	Scrutiny of Annual return on sale value, Ex. Mine price and production cost			Violation pointed out under rule 45(7) of MCDR 2017.
9h	Scrutiny of Annual return on fixed assets	Fixed assets value of Rs 27000000/-	Appear to be correct.	-
9k	Scrutiny of Annual return on mining machineries		Appear to be correct.	_

PAGE : 13

1/29266/2024

Details of violations observed during current inspection and compliance position of violation pointed out

Violation observed				Show couse position		
Rule 1	10.	Issued on	Compliance on	Rule NO.	Issued on Compliance on	
MCDR17	Rule 11(1)	31/01/2024	13/03/2024	Rule 45(7)(i)	31/01/2024 13/03/2024	
MCDR17	Rule 26(2)	31/01/2024	13/03/2024			
Rule 45	(7)(i)	31/01/2024	13/03/2024			

Date: (GANGADHAR BHAKAT)

Indian Bureau of Mines