INDIAN BUREAU OF MINES MINERALS DEVELOPMENT AND REGULATION DIVISION

MCDR inspection REPORT

Goa regional office

Mine file No : KNT/BJP/LST-58/GOA Mine code : 38KAR26025

(i) Name of the Inspecting : $V \uparrow 01$) V I D Y A D H A R V. T A R I

Officer and ID No.

(ii) Designation : Assistant Mining Engineer

(iii) Accompaning mine : S/SHRI.H.G.SHREEPADA, LESSEE & G.S.N.MURTHY, LESSEE'S R

Official with Designation

(iv) Date of Inspection : 07-SEP-23
(v) Prev.inspection date : 29-JUN-21

PART-I : GENERAL INFORMATION

. (a) Mine Name : NAGANPUR (ML 2358)

(b) Registration NO. : IBM/6167/2011

(c) Category : A Mechanised

(d) Type of Working : Opencast

(e) Postal address

State : KARNATAKA
District : BAGALKOT
Village : NAGANPUR
Taluka : MUDHOL
Post office : LOKAPUR
Pin Code : 587122

FAX No. : 08350240325

E-mail : malaprabha_mining@yahoo.com

Phone : 08350240325

(f) Police Station : Mudhol
(g) First opening date : 05-JUL-02

(h) Weekly day of rest : SUN

2. Address for : Naganpur Limestone Mine of Shri H.G.Shripad

correspondance At-Naganapur, Tq- Mudhol

Dist- Bagalkot

3. (a) Lease Number : KAR1451
(b) Lease area : 2.43
(c) Period of lease : 50

(d) Date of Expiry : 02-JUL-52

4. Mineral worked : LIMESTONE Main

5. Name and Address of the

Lessee : H. G. SHRIPAD

M/s Ashirwad Minerals "Parimala", Vidyagiri, Mahantesh Road, BAGALKOT

KARNATAKA
Phone:
FAX :

Owner : H.G.SHRIPAD

PARIMALA MAHANTESH
VIDAYAGIRI BAGALKOT
BAGALKOT KARNATAKA
Phone: 08354--233258
FAX: NIL

Mining Engineer

Name : Shri. Prakash Kaladagi,,Full Time Qualification : Diploma in Mining & Mine Surveying

Appointment/ : Termination date

Geologist

Name : Shri. Suraj M.Mense, Part Time

Qualification : M.Sc (Applied Geology)

Appointment/ : 01-MAR-22

Termination date

Manager

Name : Shri. Prakash Kaladagi,

Qualification : Diploma in Mining & Mine Surveying

Appointment/ :
Termination date

6.	Date of approval of Mining Plan/Scheme of Mining	:	Fresh under rule 22 MCR1960 Modif.of approved Mining Plan Mining Scheme rule 12 MCDR1988 Mining Scheme rule 12 MCDR1988 MP modif under 17(3) MCR 2016 MP modif under 17(3) MCR 2016	18-JUN-02 06-FEB-06 20-NOV-07 10-SEP-12 06-APR-17 27-JAN-20
			MP review under 17(1) MCR 2016	27-JAN-22

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
1a	Backlog of previous year	No Proposal in 2022-23	Nil during 2022-23	Lessee has drilled 04 boreholes for total meterage of 130m. during 2015 and 05 boreholes for total meterage of 120m. during 2019 in the mining lease area. Entire area is covered under G1 level of exploration
1b	Exploration over lease area for geological axis or 2	No exploration proposal is given for the year 2022-23.	Nil	Entire lease area is covered under G1 scale
1c	Exploration Agencies and Expenditure in lakh rupees during the year	Nil	Nil	
1d	Balance area to be explored to bring Geological axis in 1 or 2	Nil	Nil	The entire lease area is explored under G1 Stage
1e	Balance reserve as on 01/04/20		Total Reserves of Limestone is 0.86 million tonnes (UNFC Cat. 111)	As on 01.04.2023 (As per the Annual Return submitted for F.Y. 2022-23)
1f	General remarks of inspecting officers on geology, exploration etc			No exploration proposal is given for the year 2022-23. However, entire lease area is explored by lessee and covered under G1 Stage

Sl.No.	Item	Propasals	Actual work	Remarks
		_		

2a	Location of development w.r.t.lease area	Proposal is given in the existing pit as shown over Pit Layout Plan	No Change	
2b	Separate benches in topsoil, overburden and minerals (Rule 15)	Not Applicable	Not Applicable	All the benches are proposed in mineral only
2c	Stripping ratio or ore to OB ratio	1:0.00	1:0.00	There is no generation of OB during 2022-23
2d	Quantity of topsoil generation in m3	Nil	Nil	
2e	Quantity of overburden generation in m3	Nil	Nil	
2f	General remarks of inspecting officers on development of pit w.r.t. type of deposit etc			No proposal for OB / Waste generation is given during the year 2022-23. Entire lease area is mineralised. Hence, proposal for handling only limestone mineral is given.

Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
3a	Number of pit proposed for production	One pit (Four benches)	No change.	
3b	Quantity of ROM mineral production proposed	70000 tonnes during 2022-23	70000 tonnes during 2022-23	As per the Annual Return submitted for F.Y. 2022-23
3с	Recovery of sailable/usable mineral from ROM production	100%	100%	
3d	Quantity of mineral reject generation	Nil	Nil	

3e	Grade of mineral rejects generation and threshold value declared.	Nil	Nil	
3f	Quantity of sub grade mineral generation.	Nil	Nil	
3g	Grade of sub grade mineral generation	Nil	Nil	
3h	Manual / Mechanised method adopted for segregating from ROM	Mechanised	Mechanised	By deploying excavator and tipper
3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.	No	Nil	
3j	Provision of drilling and blasting in mineral benches	Drilling & blasting is proposed	Jack Hammer drilling & blasting by using slurry explosives	
3k	Provision of mining machineries in mineral benches	By deploying excavator and tipper.	No Change	
31	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	Height of the benches proposed is 5m		Average height of 5m. is maintained
3m	Total area covered under excavation/pits	1.85 Ha. upto the end of 2022-23 as per the approved RMP (plan period ending 2026- 27)	1.93 Ha. as per submitted Annual Return	
3n	Ore to OB ratio for the pit/mine during the year.	1:0.00	1:0.00	There is no generation of OB during 2022-23

30	Total area put in use under different heads at the end of year	mining 1.90 Ha. Infra	Ha. as per Annual Return
3p	Production of ROM mineral during the last five year period as applicable	Tons 19-20 = 70000 Tons	18-19 = 55000 Tons 19-20 = 35000 Tons 20-21 = 44500 Tons 21-22 = 70000 Tons 22-23 = 70000 Tons

3q General remarks of inspecting officers on method of mining etc.

Mine is proposed and reportedly operated with jack hammer drilling and blasting by using slurry explosives and deploying excavator and tipper.

Solid Waste Management - Dumping:

Sl.No.	Item	Propasals	Actual work	Remarks
4a	Separate dumping of topsoil, OB and mineral rejects (Rule 32,33)	Not proposed.	Nil	There are no separate waste dump, topsoil and mineral reject stack within ML area
4b	Location of topsoil, OB and mineral reject dumps	Not Applicable.	Nil	
4c	Number of dumps within lease area and outside of lease area	Nil	Nil	
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	Nil	Nil	

_				
4e	Number of active and alive dumps.	Nil	Nil	
4f	Number of dead dumps.	Nil	Nil	
4g	Number of dumps established.	Nil	Nil	
4h	Whether Retaining wall or garland drain all along dumps are there.	No Proposal	Nil	
4i	Length of Retaining wall or garland drain all along dumps	No Proposal	Nil	
4j	Number of settling ponds	Nil	Nil	
4k	Specific comments of inspecting officer on waste dump management			OB / Waste generation proposals are not given during the F.Y 2022-23. Entire lease area is mineralised. Proposal for handling only limestone mineral is given.

Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	Backfilling is not proposed	Nil	Mining pits are not matured for backfilling. Mineral is not exhausted from the pit.
5b	Area under backfilling of mined out area	Not proposed	Nil	
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	Nil	Nil	Generation of topsoil during 2022-23 is Nil

5d	Total area fully reclaimed and rehabilitated	Nil	Nil	
5e	General remarks of inspecting officers on backfilling and reclamation etc.			Since mineral has not been exhausted from pit / any part of the lease area, backfilling / reclamation is not envisaged

Progressive Mine Clousre Plan:

Sl.No.	Item	Propasals	Actual work	Remarks
ба	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	To be submitted before 1st July every year	Submitted for 2022-23	
6b	Area available for rehabilitation (ha).	No proposal	Not applicable	Mineral is not exhausted from the pit
6c	afforestation done (ha).	0.09 На	0.09 На	50 plants reported to be planted during 2022-23 within lease area all along 7.5m safety barrier with 40% survival rate
6d	No. of saplings planted during the year	50 plants	50 plants	Planted within lease area all along 7.5m safety barrier with 40% survival rate
6e	Cumulative no .of plants	250 plants during plan period (2022- 23 to 2026-27)	Appx. 516 nos. planted within and outside ML Area as reported by the lessee	As per the Annual Return submitted for F.Y. 2022-23
6f	Any other method of rehabilitation	No proposal	Not applicable	
бд	Cost incurred on watch and care during the year	Rs.2500/-	No change	

6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling (Lx B x D	No proposal	Not applicable	Mineral is not exhausted from the pit
6i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	No proposal	Not applicable	
6j	Compliance on reclamation and rehabilitation by backfilling (iii)Afforestati on on backfilled area	No proposal	Not applicable	
6k	Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir	No proposal	Not applicable	
61	Compliance on reclamation and rehabilitation by backfilling (v)any other specific means.	No proposal	Not applicable	
6m	Compliance of rehabilitation of waste land within lease (i)afforestation	No proposal	50 plants reported to be planted during 2022-23 within lease area all along 7.5m safety barrier with 40% survival rate	
6n	Compliance of rehabilitation of waste land within lease (ii)Area rehabilitation (ha)	No proposal	All along mining lease.boundary in 7.5m. safety zone	
60	Compliance of rehabilitation of waste land within lease (iii)Method of rehabilitation	No proposal	By plantation	

6p	Compliance of environmental monitoring (core zone and buffer zone)	done by private	Environmental monitoring is carried out periodically through approved agency and parameters are found within stipulated limit.	
бq	General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.			PMCP compliance and progressive closure is found to be satisfactory.

Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	ROM/Mineral dispatch is proposed after sizing and sorting.	No change	
7b	Method of grade- wise mineral sorting i.e. manual or mechanical.	Mechanical	No change	
7c	Different grade of mineral sorted out at mines.	Yes	BF & Cement grade Limestone is sorted out at mines	
7d	Any beneficiation process at mines .	No proposal	Crushing and screening of ROM	
7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues			During 2022-23, Cement Grade limestone was dispatched after sizing and sorting as per the requirement

Environment:

Sl.No.	Item	Propasals	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	Not Proposed	No topsoil is generated during 2022-23	

8b	Concurrent use or storage of topsoil	Not Proposed	Nil	
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	Not Proposed	No OB / waste is generated during 2022-23	
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	Not Proposed	Nil	
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	Not Proposed	Nil	
8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	Proposed to plant 50 Saplings during 2022-23	50 plants reported to be planted during 2022-23 within lease area all along 7.5m safety barrier.	
8g	Survival rate	30% to 40%	40%	
8h	Water sprinkling on roads to control airborne dust	Proposed	Water sprinkling by water tanker is being carried out.	
8i	General remarks of inspecting officer on aesthetic beauty in and around mines area			Aesthetic beauty in and around the mining area appears to be good.

Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks

9a	Status of submission of Monthly and Annual returns	M.R. Submitted up to August'2023 & A.R. for the year 2022-23 is submitted		Submitted within time limit.
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	Mines Manager - A.H.Kolachi Mining Geologist - Yogesh M.Kutre	Kaladagi Mining Geologist - Suraj H.Mense appointed since	
9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	1.930 Road, Buildings,	Road, Buildings, Infrastructure = 0.109	As per the Annual Return submitted for FY 2022-23
9d	Scrutiny of Annual return on afforestation	50 plants proposed	50 plants reported to be planted within lease area all along 7.5m. safety barrier.	
9e	Scrutiny of Annual return on mineral reject generation (Grade and quantity)	Nil	Nil	
9f	Scrutiny of Annual return on ROM stock and/or graded ore		BF Grade = 548.110 Tons and Cement Grade = 18425.400	As per the Annual Return submitted for FY 2022-23
9g	Scrutiny of Annual return on sale value, Ex. Mine price and production cost	of Cement Grade is reported as	Ex- Mine Price of Cement Grade is reported as Rs. 390.00 per tonne and Production Cost is Rs. 323.23 per tonne	As per the Annual Return submitted for FY 2022-23
9h	Scrutiny of Annual return on fixed assets	Furnished	Value of fixed asset is reported to be Rs.319766	As per the Annual Return submitted for FY 2022-23
9k	Scrutiny of Annual return on mining machineries	Mining machinery details furnished	Mining machinery details furnished	

PAGE : 13

Details of violat	ions observed duri	ing current	inspection	and compliance	position of
Violat	Sho	ow couse positi	on		
Rule NO.	Issued on Cor	mpliance on	Rule NO). Issued o	n Compliance on

Date: (VIDYADHAR V.TARI)

Indian Bureau of Mines