



भारत सरकार/Government of India
खान मंत्रालय/Ministry of Mines
भारतीय खान ब्यूरो/Indian Bureau of Mines



क्षेत्रीय खान नियंत्रक, गोवा का कार्यालय/Office of the RCOM, Goa

Phone No.: (0832)-2741757

Fax No. : (0832)-2741758

602,

E-mail : ro.goa@ibm.gov.in

Opp. R.T.O. Office,

P.O. FATORDA - 403

MARGAO - GOA.

No: MCDR-MiFLOLST/10/2023-GOA-IBM_RO_GOA

Mine Code: 38KAR26021

Date: 26/04/2024

सेवा में/ To,

Shri Shivaji Vasudeva Devagiri, Mine Owner
M/s Shri Amba Minerals
Muddapur Village
Mudhol Taluka, Bagalkot District.
Karnataka: 587 122

विषय/Subject: Violations of MCDR provisions in respect of Muddapur Limestone & Dolomite Mine (ML No. 2316/2432), Extent 10.83 Ha., situated in Muddapur Village, Mudhol Taluk, Bagalkot District of Karnataka State.

महोदय/Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during the inspection on 07.10.2023 by the undersigned in the presence of Mr Mohamed Shoheb Dangi-Mining Engineer and other mining officials:

Rules	Nature of Violations observed
11 (1)	<p>The mining operation in the leasehold area is not carried out as per the modifications in the approved Mining Plan, dated 24.06.2022 to the extent mentioned below:</p> <ol style="list-style-type: none"> Dumping of waste is not found to be carried out at designated areas. During inspection it was observed that the proposed surface dumping area has now been converted into the mineral stacking area; vis-a-vis dumping of waste is carried out in an unspecified location at south western side of the ML area, near BP-1. The bench parameters in the pit are not maintained properly. The height & width of the benches are not found as per the approved document in many places. General Cleanliness and maintenance of pit bottom & benches in the mines area is found in a meager condition. In the bottom of the pit, small and unsystematic heaps of the material were observed. Production of Limestone Ore & Mine development is reported less than the against the approved proposal 15000 Mt & 2473m³ respectively.

I/30525/2024

26 (2)	The yearly report before 1 st July of every year setting forth the extent of protective and rehabilitation work carried out as envisaged in the approved progressive mine closure plan has not been submitted for the last year 2022-23.
--------	---

02. It is brought to your notice that violation of the above Rule constitutes an offence punishable under Rule 62 of MCDR, 2017.
03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

(नरेश कुमार कटारिया)
क्षेत्रीय खान नियंत्रक,
क्षेत्रीय कार्यालय-गोवा, भारतीय खान ब्यूरो

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

(नरेश कुमार कटारिया)
क्षेत्रीय खान नियंत्रक,