# MCDR-MiFLOLST/225/2022-GNR-IBM\_RO\_GNR

### MCDR INSPECTION REPORT

## 1/5544/2023<u>1.0 **GENERAL**</u>

SN	Particulars	Details
-		
1(a)	Name of the Mine	Ranavav Limestone Mines
1(b)	Name of inspecting officer & Designation	Shri. Naman Ekka, SMG
1(c)	Accompanying Mines Respresentatives	Mr D.K.Singh
1 (d)	Type of Inspection	Star Rating
1 (e)	Date of Inspection	12/01/2023
2	Total Lease Area (Ha) with breakup of Non-	31.28 Ha. (Forest Area: Nil) (Non-forest Area:
-	forest and forest land	31.28 Ha)
3		
	Mine code	38GUJ21060
4	IBM Registration Number under rule 45 of	IBM/265/2011
	MCDR, 1988	
5	Name of the lessee, Address, phone, email and	Saurashtra Chemical, Division of Nirma Ltd.
	fax number	Porbandar, Phone : 02862242479 Fax:
		02862245431 E mail: quarry_pbr@nirma.co.in
6	Village	Ranavav
7	Taluka/Mandal	Ranavav
8	District	Porbandar
9	Pincode	360576
10	State	Gujarat
11	Post office	Ranavav
12	Nearest police station	Ranavav, Porbandar
13	Nearest Railway station	Ranavav
14	Date of Grant of Mining Lease	30.07.1981
15	Date of Execution	30.07.1981
16	Date of opening of Mine	
17	Date of first Renewal, if applicable and its period	30.07.2001 for 20 year
	& expiry	
18	Date of second Renewal, if applicable and its	
	period & expiry	
19	Date of submission of renewal application if	Period extended as per MMDR amendment act
	Mining Operations are continuing under deemed	2015 section 8A(5)(6) up to 31.03.2030
	extension	
20	Name of the Nominated Owner with Address,	Shri Sailesh V. Sonara, Executive Director,
	phone, email, fax number and date of	Saurashtra Chemical, Division of Nirma Ltd.
	appointment	Porbandar Phone No: 07927549000, Fax No:
	арропипени	07927546603, Email: mines@nirma.co.in
21	NI	
21	Name of the Mine Agent with Address, phone,	Sri Manish D Patel, Mines Agent, Saurashtra
	email, fax number and date of appointment	Chemical, Division of Nirma Ltd, Porbandar,
		Phone: 02862242479 Fax: 02862245431 E mail:
		quarry_pbr@nirma.co.in
		quarry_portermmu.co.m
22	Name of the Mines Manager with Address,	Not-appointed, due to mines not working since
	phone, email, fax number and date of	long.
	appointment in mines	10119.
23	Name of the Mining Engineer, Qualification and	Not-appointed, due to mines not working since
23		11
	total experience with Address, phone, email, fax	long.
6.4	number and date of appointment in mine	37
24	Whether Geologist and Mining Engineer	Not-appointed, due to mines not working since
	appointed in mines satisfy the rule 55 & carrying	long.
	out their duties as per rule 56 & 57.	
25	Date of Approval of Mining Plan/Modified	Letter No. 684(4)(1)/MP-140/2018
	Mining Plan/Review of mining plan with five-	MDRD(U)/GNR Dt 14.06.2018 (June'2018 to
	year period and specific condition in approval	March'2022)
	letter, if any.	
26	Date of Approval of Scheme of Mining/Modified	
20	Scheme of Mining with five-year period and	
27	specific condition in approval letter, if any.	T
27	Mineral(s) granted in lease and proved for	Limestone
<u> </u>	mining	
28	Method of Mining(Opencast, Underground)	Opencast
29	Category (Fully Mechanised, Others or Manual)	'A'
30	Captive/Non Captive	Captive

Scientific Mining: Compliance of proposals of approved mining plan/scheme of mining. —

Exploration

-APIO	I UUVII			
SN	Item	Proposals (2020-21)	Actual work	Remarks
1a	Backlog of previous year	N.A.	N.A.	
1b	Exploration over lease area for	Not Proposal.	NA	
	Geological axis 1 or 2.			
1c	Exploration Agency &	Not Proposal.	Nil	
	Expenditure in lakh Rupees			
	during the year			
1d	Balance area to be explored to	Not Proposal.	Nil	
	bring Geological axis in 1 or 2			
1e	Balance reserves as on	Chemical grade-13,60,000	Chemical grade-	
	01.04.2021	MT (As per UNFC 111,121	13,60,000 MT (As	
		and 122) as per mining plan	per UNFC 111,121	
		as on 01.06.2018	and 122) as per annual	
			return as on	
			01.04.2021	
1f	General remarks of inspecting	Presently mine is not working due to want of statutory clearance		
	officer on geology, exploration	& long back.		
	etc.			

2.0 Development

_,,	· veropriterit			
SN	Item	Proposals(2020-21)	Actual work	Remarks
2a	Location of development w.r.t. lease area	Existing pit	Nil	During
2b	Separate benches in topsoil, overburden and mineral (Rule 15)	N.A.	N.A.	inspection Mines was not working.
2c	Stripping ratio or ore to OB ratio	1:0	1:0	
2d	Quantity of topsoil generation in m3	1146	Nil	
2e	Quantity of overburden generation in m3	N.A.	N.A.	
2f	General remarks of inspecting officer on development of pit w.r.t. type of deposit etc.	Mining lease area is de fully water logged.	veloped by degr	aded mine pit &

3.0 Exploitation

SN	Item	Proposals (2020-21)	Actual work	Remarks
3a	Number of pits proposed for production	Existing pit		
3b	Quantity of ROM mineral production proposed	200000	Not done.	
3c	Recovery of salable/usable mineral from ROM production	170000	Not done.	
3d	Quantity of mineral reject generation	NIL	NIL	
Зе	Grade of mineral reject generation and threshold value declared	N.A	N.A.	
3f	Quantity of sub-grade mineral generation	20000	Not done.	
3g	Grade of sub-grade mineral generation	Undersize Chemical Grade Limestone	NIL	
3h	Manual / Mechanised method adopted for segregating from ROM	Manual	NIL	
3i	Any analysis or beneficiation study proposed & carried out for sub-grade mineral and reject	N.A.	N.A.	
3j	Provision of drilling & blasting in mineral benches	YES	NIL	
3k	Provision of mining machineries in mineral benches	YES	NIL	
31	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	There is no Overburden in mining area and height of benches in mineral is suitable for method of Mining proposed in RMP	NIL	
3m	Total area covered	15.25 Ha	11.789 Ha	

## MCDR-MiFLOLST/225/2022-GNR-IBM\_RO\_GNR

1/5544	/2M23
1/ 3344	/ LULJI

		under excavation/pits		
3	3n	Ore to OB ratio for the pit/mine during	1:0	NIL
		the year		
	3о	Total area put in use under different	Pit-11.789 Ha	Pit-11.789
		heads at the end of year	Waste/reject–Nil	Ha
			Others-1.05 Ha	Waste/
			Plantation- 0.30 Ha	reject–Nil
				Others-1.05
				Ha
				Plantation-
				0.30 Ha
	Зр	Production of ROM mineral during last	Yr 2016-17 200000	NIL
		five-year period, as applicable	Yr 2017-18 200000	
			Yr 2018-19 200000	
			Yr-2019-20- 200000	
			Yr 2020-21- 200000 MT	
	3q	General remarks of inspecting officer on	Presently mine is not working d	ue to want of statutory
		method of mining etc.	clearance & long back.	-

4.0 Solid Waste Management-Dumping

<u>4.0 50</u>	lid Waste Management-Dumping			
SN	Item	Proposals (2020-21)	Actual work	Remarks
4a	Separate dumping of topsoil, OB &	NIL	NIL	
	mineral reject (Rule 32, 33)			
4b	Location of topsoil, OB & mineral	N.A.	N.A.	
	reject dumps			
4c	Number of dumps within lease area	NIL	NIL	
	and outside lease area			
4d	Location of dumps w.r.t. ultimate pit	N.A.	N.A.	
	limit (Rule 16)			
4e	Number of active & alive dumps	NIL	NIL	
4f	Number of dead dumps	N.A.	N.A.	
4g	Number of dumps stabilished	N.A.	N.A.	
4h	Whether Retaining wall or garland	N.A.	N.A.	
	drain all along dumps are there			
4i	Length of Retaining wall or garland	N.A.	N.A.	
	drain all along dump			
4j	Number of settling ponds	N.A.	N.A.	
4k	Specific comments of inspecting	The mining lease area appears to be devoid of OB/Waste.		OB/Waste.
	officer			

**5.0 Solid Waste Management-Backfilling** 

SN	Item	Proposals (2020-21)	Actual work	Remarks
5a	Status on part or full extraction of mineral	Partial	NIL	
	from mined out area before starting			
	backfilling			
5b	Area under backfilling of mined out area	NIL	NIL	
5c	Concurrent use of topsoil for restoration or	Plantation	Nil	Plantation
	rehabilitation of mined out area (Rule 32)			work is good.
5d	Total area fully reclaimed & rehabilitated	Nil	Nil	
5e	General remarks of inspecting officer on	The mining lease area appears to be devoid of		
	backfilling, reclamation etc	OB/Waste. Hence not applicable.		

6.0 Progressive Mine Closure Plan

SN	Item	Proposals (	(2020-21)	Actual wo	rk	Remarks
6a	Whether Annual report on	YES		YES		
	PMCP submitted on time and					
	correctly - Rule 26(2). Details					
	should be given in the format					
	as given in Annexure-20.					
6b	Management of worked/mined	i)	N.A.	i)	N.A.	
	out benches	ii)	NO	ii)	0.1 Ha	
	i) Area available for	iii)	NO	iii)	200	
	rehabilitation (ha)	iv)	No		Nos	
	ii) Afforestation done (ha)	v)	No	iv)	2300	
	iii) No. of saplings planted	vi)			Nos	
	during the year			v)	No	

## ${\sf MCDR-MiFLoLST/225/2022-GNR-IBM\_RO\_GNR}$

1/5544/2023
-------------

3	iv) Cumulative no. of plants v) Any other specific method of rehabilitation vi) Cost incurred on watch & care during the year		vi) Rs 10000/ -	
6c	Compliance on reclamation and rehabilitation by backfilling i) Voids available for backfilling (L X B X D) ii) Void filled by waste/tailings iii) Afforestation on the backfilled area iv) Rehabilitation by making water reservoir v) Any other specific means	No reclamation is proposed by means of backfilling as no waste material is available	No reclamation is proposed by means of backfilling as no waste material is available	
6d	Compliance of Rehabilitation of waste land within lease i) Afforestation ii) Area rehabilitated (ha) iii) Method of rehabilitation	No waste Land is available within lease area	No waste Land is available within lease area	
6e	Compliance of Environmental monitoring (core zone & buffer zone)	Ambient Air Monitoring, Water quality monitoring and Noise monitoring	Ambient Air Monitoring, Water quality monitoring and Noise monitoring is being done on half yearly basis and soil monitoring on yearly basis.	
6f	General remarks of inspecting officer on PMCP compliance & progressive	Presently mine is not working Clearance & long back. Hence	g due to want of statuto	

#### 7.0 Mineral Conservation

2.00 172	merar conservation			
SN	Item	Proposals (2020-21)	Actual work	Remarks
7a	ROM Mineral dispatch or grade-	200000	NIL	
	wise sorting within lease area			
7b	Method of grade-wise mineral	Manual	NIL	
	sorting i.e. manual or mechanical			
7c	Different grade of mineral sorted	Only undersize Limestone is		
	out at mines	available as subgrade mineral		
		and stacked at pit floor	NIL	
7d	Any beneficiation process at mines	No	No	
7e	General remarks of inspecting	Presently mine is not working due to want of statutory		
	officer on Mineral conservation &	clearance & long back. Presently mining lease area appears to		
	beneficiation issues	be devoid of		
		OB/Waste.		

#### 8.0 Environment

0.0 Environment						
SN	Item	Proposals (2020-21)	Actual work	Remarks		
8a	Separate removal and utilization of	No Proposal	N.A.			
	topsoil (Rule 32)					
8b	Concurrent use or storage of topsoil	Plantation	Plantation			
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	No Proposal	No Proposal			
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	N.A.	N.A.			

### MCDR-MiFLOLST/225/2022-GNR-IBM\_RO\_GNR

1/5544/2023

	8e	Phased restoration, reclamation and	Mined out pits will	Pits are being used	
3		rehabilitation of lands affected by	be utilized as rain	for rain water	
		mining operations (Pits, dumps etc)	water storage	harvesting	
	8f	Baseline information on existence of	NA	NA	
		plantation & additional plantation			
		done (Rule 41)			
	8g	Survival rate	100 %	50 %	
	8h	Water sprinkling on roads to control	Water sprinkling on	Water sprinkling	
		airborne dust	road will be done	on road will be	
			through water tanker	done through	
				water tanker	
	8i	General remarks of inspecting	Mining lease area is degraded old pit & surrounding ML area is		
		officer on aesthetic beauty in and	mostly agriculture land.		
L		around mines are			

**दिनांक** / Date: 27/02/2023

9.0 Compliance of Rule 45								
S. N.	Item	COMMENTS		Remarks				
9a	Status of submission of Online Monthly and Annua returns	M.R. Submitted up to till 2022 A.R. submitted up to till	-					
S. N.	Item	Details GIVEN in A.R. (2021-22)	Observation of I/Officer /Actual reported in Returns	Remarks				
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	NA		During inspection Mines was not working.				
9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	Covered Under Current working- 11.789 Ha/ Afforestation/ plantation - 0.140 Ha	Covered Under Current working- 11.789 Ha/ Afforestation/ plantation -0.140 Ha					
9d	Scrutiny of Annual return on afforestation	Afforestation/ plantation - 0.140 Ha	Afforestation/ plantation -0.140 Ha					
9e	Scrutiny of Annual return on mineral reject generation (Grade & quantity)	NIL	NIL					
9f	Scrutiny of Annual return on ROM stock and/or graded ore	3166.060 Mt	3166.060 Mt					
9g	Scrutiny of Annual return on sale value, Ex. Mine price & production cost	<ol> <li>Ex.Mine Prise -NIL</li> <li>Cost of production- NIL</li> </ol>	Ex. Mine prise-NIL     Cost of production     on-NIL					
9i	Scrutiny of Annual return on fixed assets	Industrial -253690 Residential-0	Industrial -253690 Residential-0					
9k	Scrutiny of Annual return on mining machineries	NIL	NIL					

<sup>10-</sup> Details of violations observed during current inspection and compliance position of earlier violation pointed out:- Presently no significant violation observed & pointed out to lessee.

(Naman Ekka) Sr. Mining Geologist