MCDR INSPECTION REPORT

l/30771/2024 **General:**

Sl.N	Particulars	Details
1	Name of the Mine	Nandini-Khundini Limestone Mine
2	Date of Inspection:	25.09.2023
3	Name of Inspection. Name of Inspecting Officer & Designation	Soumallya Roy, AME
4	Name of official accompanying inspection	Shri Amit Kashyap, Representative of
4	rvaine of official accompanying inspection	Mine owner
5	Last date of Inspection & Officer	18.01.2023, Shri Debadurllav Das, RMG
6	Total Lease Area (Ha) with breakup of Non-forest and forest land	Non-forest land- 4.55 Ha.
7	Mine code	38MPR13024
8	IBM Registration Number under rule 45 of MCDR, 1988/2017	IBM/5674/2011
9	Name of the Lease, Address, Phone, email and fax number	Smt. Mohini Devi Mishra , 48/3,Nehru Nagar, Bhilai, District- Durg (C.G) 490020
10	Village	Nandini Khundini
11	Taluka/Mandal	Dhamdha
12	District	Durg
13	Pin code	490036
14	State	Chhattisgarh
15	Post Office	Nandini Nagar
16	Nearest Police Station	Nandini Nagar
17	Nearest Railway Station	Durg
18	Date of Grant of Mining Lease	14.06.1993
19	Date of Execution	14.06.1993
20	Weekly day of rest	Sunday
21	Date of opening of Mine	01.08.1993
22	Date of First Renewal, if applicable and its period & expiry	As per section 8A of MMDR Amendment Act, 2015, the lease period has been extended up to 50 years i.e upto 13.06.2043.
23	Date of Second Renewal, if applicable and its period & expiry	NA
24	Date of submission of renewal application if Mining Operations are continuing under deemed extension	NA
25	Name of the Nominated Owner with Address, phone, email, fax number and date of appointment	Smt. Mohini Devi Mishra , 48/3,Nehru Nagar, Bhilai, District- Durg (C.G) 490020
26	Name of the Mine Agent with Address, phone, email, fax number and date of appointment	Not appointed.
27	Name of the Mine Manager with Address, phone, email, fax number and date of appointment in mines	Not appointed.
28	Name of the Mining Engineer, Qualification and total experience with address, phone, email, fax number and date of appointment in the mine	Mr. Raju Kumar Tandi
29	Whether Geologist and Mining Engineer appointment in mines satisfy the rule 55 & carrying out their duties as per provision of MCDR 2017.	Mr. Santosh Kumar Funde, Geologist
30	Date of Approval of Mine Plan/Modified Mine Plan with five- year period and specific condition in	Letter no. DRG/LST/MPLN-07/NGP, dated

1/30771/2024

	approval letter, if any.	14/01/1990, Letter no. DRG/LST/MPLN-07/NGP, dated 14/06/2013
31	Date of Approval of Scheme of Mining/Modified Scheme of Mining/ Review of Mining plan with five- year period and specific condition in approval letter, if any.	Review of Mining Plan approved vide letter no. DRG/LST/KHYO-1151/2018, dated 25/05/2018 Proposal Period: 2022-23 to 2026-27
32	Mineral(s) granted in lease and approved for Mining	Limestone
33	Method of Mining (Opencast, Underground)	Open Cast
34	Category (Fully Mechanized, Others or Manual)	Category "A"
35	Captive/Non-Captive	Non Captive
36	Present EC Status	40, 000 Tonne per Annum
37	Status of Financial Assurance	Bank Guarantee of Rs.12,75,000/-valid up to 27/03/2023.

Scientific Mining: Compliance of proposals of approved Mining Plan/Review of Mining Plan: 1.0 Exploration:

	apioration.			
S. N.	Item	Proposals (2022-23)	Actual Work(2022- 23)	Remarks
1a	Backlog of previous year Proposals	Nil	Nil	
1b	Exploration over lease area for Geological axis 1 or 2.	Not proposed	Nil	As per the approved
1c	Exploration Agency & Expenditure in Lakh Rupees during the year	Not proposed	Nil	document 3.80 Ha. area
1d	Balance area to be explored to bring Geological axis in 1 or 2.	Not proposed	Nil	Covered under G1 and
1e	Balance reserves as on 01.04.2023	Under 121- 334499 T (As on 31.03.2018)	Balance reserves as on 01.04.2023: Under 121- 332999 T	remaining 0.75 covered under G2 area.
1f	General remarks of Inspecting officer on geology, exploration etc.	Entire lease area is explored under G1 level as per approved review of Mining plan. Mines was suspended by this office vide letter no. CHG/RAP/LST-27/Raipur/333 dated 04.10.2023 under Rule 11(1) 7& 26 (2) of MCDR 2017.		

2.0 Development:

S.	Item	Proposals (2022-23)	Actual	Remarks
N.			Work(2022-23)	
2a	Location of Development w.r.t.	Within the present pit.	Within the present	Production is
	lease area		pit. Also 7.5m	less due to
			safety barrier	lack of
			zone was found	demand. No
			encroached by	OB/mineral
			extension of	reject
			quarry.	generated
2b	Separate benches in topsoil	Benches in topsoil/OB	Only mineral	during this
	overburden and mineral (Rule	not Proposed during	bench present.	year.

1/30771/2024

	15)	the year.		
2c	Stripping ratio or ore to OB	Nil	Nil	
	ratio			
2d	Quantity of topsoil generation in	Nil	Nil	
	m3			
2e	Quantity of overburden	Nil	Nil	
	generation in m3			
2f	General remarks of Inspecting	Mines was suspended b	y this office vide lette	er no.
	officer on development of pit	CHG/RAP/LST-27/Raipur/333 dated 04.10.2023 under		
	w.r.t type of deposit etc.	Rule 11(1) 7& 26 (2) of MCDR 2017.		
		, ,		

3.0 Exploitation:

S. N.	Item	Proposals (2022- 23)	Actual Work (2022-23)	Remarks
3a	Number of pits proposed for production	01 Pit	01 Pit	
3b	Quantity of ROM mineral production proposed	39750 T	700 T	Very low production due to poor market demand.
3c	Recovery of Salable/usable mineral from ROM production.	100%	100 %.	
3d	Quantity of mineral reject generation.	Nil	No mineral reject generation.	
3e	Grade of mineral reject generation and threshold value declared.	-	Not applicable	
3f	Quantity of sub-grade mineral generation	Nil	Not applicable	
3g	Grade of sub-grade mineral generation.	Nil	Not applicable	
3h	Manual/Mechanized method adopted for segregation from ROM.	Mecchanized	Mecchanized	There is no top soil and OB generation during the year.
3i	Any analysis or beneficiation study proposed & carried out for sub-grade mineral and reject.	Not proposed	Not applicable	
3j	Provision of drilling & blasting in mineral benches.	Proposed	As proposed	
3k	Provision of mining machineries in mineral benches	Proposed	As proposed	
31	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	Mineral bench height-3 m and bench width – more than 3.0 m	As proposed	There is no top soil and OB generation during the year.
3 m	Total area covered under excavation /pits	3.95 Ha during plan period.	Approx 3.95 Ha. covered under pits.	
3n	Ore to OB ratio for the	Nil	Nil	

1/30771/2024

	pit/mine during the year			
30	Total area put in use under different heads at the end of year	Total area put in use 2.448 Ha	Approx 3.95 Ha. covered under pits.	
Зр	Production of ROM mineral during last five-	34839 T (2018- 19)	0 T (2018-19)	
	years period, as Applicable (tonne)	36488 T (2019- 20)	0 T (2019-20)	
		39750 T (2020- 21)	0 T (2020-21)	
		39750 T (2021- 22)	800 T (2021-22)	
		39750 T (2022- 23)	700 T (2022-23)	
3q	General remarks of inspecting officer on method of mining etc	There is no top soil	and OB generation du	ring the year.

4.0 Solid Waste Management-Dumping:

S. N.	Item	Proposals (2022- 23)	Actual Work (2022- 23)	Remarks
4a	Separate dumping of topsoil, OB & mineral reject (Rule 32,33)	Not proposed.	Nil.	
4b	Location of topsoil, OB & mineral reject dumps	Not proposed.	Nil.	
4c	Number of Dumps within lease area and outside lease area	Nil.	Nil.	
4d	Location of Dumps w.r.t. ultimate pit limit (Rule 16)	Within lease area.	Within lease area.	
4e	Number of Active & Alive dumps	Nil.	Nil.	
4f	Number of dead dumps	Nil.	Nil.	There is no top soil /mineral
4g	Number of dumps established	Nil.	Nil.	reject and OB generated
4h	Whether Retaining wall or garland drain all along dumps are there	Not proposed	Not applicable	during the year.
4i	Length of Retaining wall or garland drain all along dump	Not proposed	Not applicable	
4j	Number of settling ponds	Not proposed	Not applicable	
4k	Specific commends of	There is no top soil	and OB/mineral reject	generated during
	inspecting officer on waste dump management	the year.		

5.0 Solid Waste Management-Backfilling:

S.	Item	Proposals (2022-	Actual Work	Remarks
N.		23)	(2022-23)	
5a	Status on part or full extraction	Nil	Nil	There is no top
	of mineral from mined out area			soil and OB

1/30771/2024

5b	before starting backfilling Area under backfilling of mined out area	Nil	Nil	generation. Area is not matured for
5c	Concurrent use of topsoil for restoration or rehabilitation of mined out area (Rule 32)	Not proposed	Nil	reclamation and rehabilitation. No area is mined
5d	Total area fully reclaimed & rehabilitated	Not proposed	Nil	out.
5e	General remarks of inspecting officer on backfilling, reclamation etc.	There is no top soil	and OB generation.	

6.0 Progressive Mine Closer Plan:

S.	Item	Proposals (2022-	Actual	Remarks
N.		23)	Work(2022-23)	
6a	Whether Annual report on PMCP submitted on time and correctly-Rule 26 (2)	Yes.	Not submitted.	Mines was suspended by this office vide letter
6b	Management of worked/mined out benches	Nil	Nil	no. CHG/RAP/LST-
	Area available for rehabilitation (Ha)	Nil	Nil	27/Raipur/333 dated 04.10.2023 under Rule 11(1) 7& 26 (2) of MCDR 2017.
	Afforestation done (ha)	Nil	Nil	As per AR.
	No. of saplings planted during the year	Nil	50	
	Cumulative no. of plants	Nil	40	

1/30771/2024

	Any other specific method of rehabilitation	Nil	Not furnished.	
	Cost incurred on watch & care during the year	Nil	Not furnished.	
6c	Compliance on reclamation and rehabilitation by backfilling Voids available for backfilling (L*B*D) Void filled by waste/tailings Afforestation on the backfilling Rehabilitation by making water reservoir Any other specific means	Nil	No area is mined out.	No area is mined out.
6d	Compliance of Rehabilitation of waste land within lease i. Afforestation ii. Area rehabilitation (ha) iii. Method of rehabilitation	Not proposed.	Nil	
6e	Compliance of Environment monitoring (core zone & buffer zone)	Proposed.	Nil	
6f	General remarks of inspecting officer on PMCP compliance & progressive closer operations	year. No area is min office vide letter no	/OB/ mineral reject g ned out. Mines was su . CHG/RAP/LST-27/ ule 11(1) 7& 26 (2) o	spended by this Raipur/333 dated

7.0 Mineral Conservation:

S.	Item	Proposals (2022-	Actual Work (2022-	Remarks
N.		23)	23)	
7a	ROM mineral dispatch or	39750 T	700 T	The production is
	grade wise sorting within			less in
	lease area			comparison to
7b	Method of grade-wise	Nil	Nil	proposal due to
	mineral sortingi.e. manual or			lack of market
	mechanical			demand.
7c	Different grade of mineral	ROM Mineral	ROM Mineral	
	sort out at mine	dispatch.	dispatch.	
7d	Any beneficiation process at	Not Proposed	NA	
	mines			
7e	General remarks of	The production is less in comparison to proposal due to lack		
	inspecting officer on Mineral	of market demand.		
	conservation & beneficiation			
	issues			

8.0 Environment:

S.	Item	Proposals (2022-	Actual Work (2022-	Remarks
N.		23)	23)	
8a.	Separate removal and	Not Proposed.	Nil	
	utilization of topsoil			
	(Rule32)			
8b.	Concurrent use or storage of	Not proposed.	Nil	
	topsoil			
8c.	Separate dumps for	Not proposed.	Nil	
	overburden waste rock,			There is no top
	rejects and fines (Rule 33)			soil and OB

1/30771/2024

8d.	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	Not proposed.	Nil	generation.
8e.	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	Nil	Nil	
8f.	Baseline information on existence of plantation & additional plantation done (Rule 41)	Not furnished.	50 no.	

8g.	Survival rate	Not mentioned.	80%	
8h.	Water sprinkling on roads to	proposed	Observed.	
	control airborne dust			
8i.	General remarks of inspecting officer on	There is no top soil and OB generation.		
	aesthetic beauty in and around mine area			

9.0 Compliance of Rule 45:

SN	Item	Comments		Remarks
9a	Status of submission of monthly and Annual returns	MR submitted upto August 2023.		AR & MR submitted regularly.
		AR submitted for 2022-23.		
SN	Item	Details Given in A.R.	Observation of I/ Officer	
9a	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	Details of Mining Engineer & Geologist furnished.	Mining Engineer & Geologist present during inspection.	-
9b	Scrutiny of Annual return on afforestation	Within lease area 50, Survival Rate 80%	Mentioned in AR.	
9c	Scrutiny of Annual return on mineral reject generation (Grade & Quantity)	Nil	Nil	
9d	Scrutiny of Annual return on ROM stock and/or grade ore	Closing stock- 8008.060 T	Appears to be correct.	
9e	Scrutiny of Annual return on sale value, Ex. Mine price & production costs	Ex. Mine price Rs 435.00/-	Non-captive consumption.	
9f	Scrutiny of Annual return on Fixed assets	No fixed assets reported	No fixed assets reported.	
9g	Scrutiny of Annual return on mining Machineries	Dumper	Observed deployed	

1/30771/2024 <u>10. Details of violations observed during inspection</u>

No violation pointed out during inspection. Mines was already suspended by this office vide letter no. CHG/RAP/LST-27/Raipur/333 dated 04.10.2023 under Rule 11(1) 7& 26 (2) of MCDR 2017.

Signature: Name: (S. Roy) Designation: AME