MCDR

1.0 GENERAL

SN	Particulars	Details
1 (a)	Name of the Mine	Malavada Limestone Mines
1 (b)	Name of Inspecting officer & Designation	Mohammad Nimar (DCOM)
1 (c)	Accompanying Mines Representatives	Chandradev Prakash Thakore
1 (d)	Type of Inspection	Mining Plan, MCDR & Star Rating
1 (e)	Date of Inspection	15/10/2024
2	Total Lease Area (Ha) with breakup of Non-forest and forest land	4.9 Hectare
3	Minecode	38GUJ07077
4	IBM Registration Number under rule 45 of MCDR, 1988	IBM/6653/2011
5	Name of the lessee, Address, phone, email and fax number	Chandradev Prakash Thakore, THAKORE FARM N.H 8B DHORAJI ROAD NEAR UPLETA BYE PASS BOARD, UPLETA, chandradevpthakore@gmail.com , 9099028311
6	Village	Malavada
7	Taluka/Mandal	JamJodhpur
8	District	Jamnagar
9	Pincode	360490
10	State	Gujarat
11	Post office	Upleta
12	Nearest police station	Upleta
13	Nearest Railway station	Jam Jodhpur (WR 59 KM)
14	Date of Grant of Mining Lease	25-01-2005
15	Date of Execution	09-03-2006
16	Date of opening of Mine	02-10-2006
17	Date of first Renewal, if applicable and its period & expiry	09-03-2006 TO 08-03-2036
18	Date of second Renewal, if applicable and its period & expiry	N/A
19	Date of submission of renewal application if Mining Operations are continuing under deemed extension	09-03-2006 TO 08-03-2036
20	Name of the Nominated Owner with Address, phone, email, fax number and date of appointment	Chandradev Prakash Thakore
21	Name of the Mine Agent with Address, phone, email, fax number and date	Nil

	of appointment	
22	Name of the Mines	Nil
	Manager with Address,	
	phone, email, fax number	
	and date of appointment in	
	mines	
23	Name of the Mining	Nil
	Engineer, Qualification	
	and total experience with	
	Address, phone, email, fax	
	number, and date of	
	appointment in mine	
24	Whether Geologist and	BHAIRO PRASAD VERMA
	Mining Engineer appointed	
	in mines satisfy the rule 42	
	& carrying out their duties	
	as per rule 43 & 44.	
25	Date of Approval of	684(4)(1)/MP-331/2021
	Mining Plan/Modified	-22 GNR/1369 dated 07/08/2021: 01/04/2021 to
	Mining Plan with five-year	31/03/2024
	period and specific	
	condition in approval	
26	letter, if any.	
26	Date of Approval of Scheme of	C04(4)(1)/M/D 222/2021
		684(4)(1)/MP-333/2021
	Mining/Modified Scheme	-22 GNR/1383 dated 01/08/2021 01/08/2021 to 31/03/2025
	of Mining with five-year period and specific	01/00/2021 01/00/2021 t0 31/03/2023
	condition in approval	
	letter, if any.	
27	Mineral(s) granted in lease	Limestone
- '	and proved for mining	Limestone
28	Method of Mining	Opencast
	(Opencast, Underground)	- Spendage
29	Category (Fully	Mechanised.
	Mechanised, Others or	
	Manual)	
30	Captive/Non-Captive	Non-Captive

Scientific Mining: Compliance of proposals of approved mining plan/scheme of mining. – **Exploration**

LAPI	oi ativii			
S	Item	Proposals of (2023-	Actual work	Remarks
N		24)		
1a	Backlog of previous year	Not proposed	Not applicable	NA
1b	Exploration over lease area	Nil.	G1-4.9 Ha	NA
	for Geological axis 1 or 2.			
1c	Exploration Agency &	Not proposed	Not applicable	NA
	Expenditure in lakh Rupees			
	during the year			
1d	Balance area to be explored	Not proposed	Not applicable	NA

	to bring Geological axis in 1 or 2			
1e	Balance reserves as on 01.04.2024	369044.5 MT	435,043.50MT	NA
1f	General remarks of inspecting officer on geology, exploration etc.	Total lease area is ex because of no produc		*

2.0 Development

S	Item	Proposals of (2023-	Actual work	Remark
N		24)		S
2a	Location of development	SW part	21°48'55.63"N	
	w.r.t. lease area		70° 4'33.74"E	
2b	Separate benches in	Topsoil, overburden	Topsoil, overburden	
	topsoil, overburden and	Not proposed. In	Not proposed. In	
	mineral (Rule 15)	mineral 6 x 6 m	mineral 6 x 6 m	
2c	Stripping ratio or ore to	1:0	1:0	
	OB ratio			
2d	Quantity of topsoil	Nil	Nil	
	generation in m3			
2e	Quantity of overburden	Not proposed	Not Applicable	
	generation in m3			
2f	General remarks of			
	inspecting officer on	No mining operations were carried out due to		
	development of pit w.r.t.	Environmental Clearance issue.		
	type of deposit etc.			

3.0 Exploitation

S	Item	Proposals of (2023-	Actual work (2023-	Remarks
N		24)	24)	
3a	Number of pits proposed	Pit 1	Nil (Approx Pit	
	for production		Size 70*60*5)	
3b	Quantity of ROM	59160 MT	10 MT	NIL
	mineral production			
	proposed			
3c	Recovery of	56202	Nil	
	saleable/usable mineral			
	from ROM production			
3d	Quantity of mineral reject	2958 MT	Nil	
	generation			
3e	Grade of mineral reject	Not proposed	Not applicable	-
	generation and threshold			
	value declared			
3f	Quantity of sub-grade	Not proposed	Not applicable	-
	mineral generation			
3g	Grade of sub-grade	Not proposed	Not applicable	-
	mineral generation			
3h	Manual / Mechanised	Mechanised	Mechanised	-
	method adopted for			
	segregating from ROM			
3i	Any analysis or	Not proposed	Not applicable	-

	beneficiation study proposed & carried out for sub-grade mineral and reject			
3j	Provision of drilling & blasting in mineral benches	Not proposed	Not applicable	-
3k	Provision of mining machineries in mineral benches	Back hoe, Dumper, Loader	Not used	-
31	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	Yes	Yes	-
3 m	Total area covered under excavation/pits	1.9131 Ha,	0.44	-
3n	Ore to OB ratio for the pit/mine during the year	1:0	1:0	-
30	Total area put in use under different heads at the end of year	1.9131	0.44	-
3p	Production of ROM mineral during last five-year period, as applicable	22162 MT	10 MT	-
3q	General remarks of inspecting officer on method of mining etc.	No mining operations Environmental Clears	s were carried out due ance issue.	to

4.0 Solid Waste Management-Dumping

S N	Item	Proposals of (2023- 24)	Actual work (2023- 24)	Remarks
4a	Separate dumping of topsoil, OB & mineral reject	NA, No mines waste, concurrent use of 2208 cum topsoil for plantation was proposed.	No work carried out	NA
4b	Location of topsoil, OB & mineral reject dumps	Topsoil-Nil Mineral Reject – 1479	Topsoil-Nil Mineral Reject – Nil	
4c	Number of dumps within lease area and outside lease area	Not proposed	Not applicable	
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	Not proposed	Not applicable	
4e	Number of active & alive dumps	Not proposed	Not applicable	
4f	Number of dead dumps	Not proposed	Not applicable	
4g	Number of dumps	Not proposed	Not applicable	

	established			
4h	Whether Retaining wall or garland drain all along	Not proposed	Not applicable	
	dumps are there			
4i	Length of Retaining wall or garland drain all along	Not proposed	Not applicable	
	dump			
4j	Number of settling	Not proposed	Not applicable	
	ponds			
4k	Specific comments of	No work carried out due to Environmental Clearance		
	inspecting officer	issue.		

5.0 Solid Waste Management-Backfilling

SN	Item	Proposals of (2023-	Actual work	Remarks
		24)	(2023-24)	
5a	Status on part or full extraction of mineral from	Not proposed	Not applicable	-
	mined out area before			
	starting backfilling			
5b	Area under backfilling of	Not proposed	Not applicable	
	mined out area			
5c	Concurrent use of topsoil	Concurrent use of	No work carried	
	for restoration or	2208 cum topsoil for	out	
	rehabilitation of mined out	plantation was		
	area (Rule 32)	proposed.		
5d	Total area fully reclaimed &	Not proposed	Not applicable	
	rehabilitated			
5e	General remarks of	NO work carried out du	e to Environmental (Clearance
	inspecting officer on	issue.		
	backfilling, reclamation etc			

<u>.6.0 Progressive</u> Mine Closure Plan

SN	Item	Proposals of (2023-24)	Actual work	Remarks
			(2023-24)	
6a	Whether Annual report on	Yes	Submitted on 30-	-
	PMCP submitted on time		06-2024 along	
	and correctly - Rule 26(2).		with Annual	
	Details should be given in		Return	
	the format as given in			
	Annexure-20.			
6b	Management of			
	worked/mined out benches		(i) Plantation in	
	i) Area available for	(i) Plantation in	periphery of	
	rehabilitation (ha)	periphery of the	the lease area	
	ii) Afforestation done (ha)	lease area = 0.1125	= 0. 0.067 Ha.	
	iii) No. of saplings planted	Ha.	(ii) 0.0225	
	during the year	(ii) 0.0225	No.	
	iv) Cumulative no. of	(iii) 150 No	(iii) 150 No	
	plants	(iv) Nil	(iv) Nil	

	v) Any other specific method of rehabilitation vi) Cost incurred on watch & care during the year	(v)Rs. 25000/-	(v) Rs. 25000/ -	
6c	Compliance on reclamation and rehabilitation by backfilling i) Voids available for backfilling (L X B X D) ii) Void filled by waste/tailings iii) Afforestation on the backfilled area iv) Rehabilitation by making water reservoir v) Any other specific means	Not proposed	Not applicable	-
6d	Compliance of Rehabilitation of waste land within lease i) Afforestation ii) Area rehabilitated (ha) iii) Meth of of rehabilitation	Not proposed	Not applicable	-
6e	Compliance of Environmental monitoring (core zone & buffer zone)	Core Zone within limit – Ambient Air Quality, Surface water Quality, Ground water quality, Noise level, Noise vibration to be monitor and should be in limit.	Through outside agency.	-
6f	General remarks of inspecting officer on PMCP compliance & progressive	PMCP works carried out monitoring reports are wi		ironmental

7.0 Mineral Conservation

SN	Item	Proposals of (2023-24)	Actual work (2023-24)	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	95893 Tonne	10	NIL
7b	Method of grade-wise	Mechanised and	Nil	NIL

	mineral sorting i.e. manual	Manual breaking and	Mechanised	
	or mechanical	Segregation		
		Mechanised		
7c	Different grade of mineral	Not proposed	Not applicable	NIL
	sorted out at mines			
7d	Any beneficiation process			
	at mines			
7e	General remarks of	No production and dispatch activities carried out. No issue towards		
	inspecting officer on	Mineral Conservation found.		
	Mineral conservation &			
	beneficiation issues			

8.0 Environment

S	Item	Proposals of (2023-24)	Actual work (2023-24)	Remarks
8a	Separate removal and utilization of topsoil	Not proposed	Not applicable	NIL
8b	Concurrent use or storage of topsoil	Not proposed	Not applicable	NIL
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 37(1))	Not proposed	Not applicable	NIL
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	Not proposed	Not applicable	NIL
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	Not proposed	Not applicable	NIL
8f	Baseline information on existence of plantation & additional plantation done (Rule 41)	300	300	NIL
8g	Survival rate	50%	50%	Nil
8h	Water sprinkling on roads to control airborne dust	Yes	Nil	NIL
8i	General remarks of inspecting officer on aesthetic beauty in and around mines are	PMCP work done as proposed. Mine is surrounded by nearby villages with green vegetation.		

S. N.	Item	COMMENTS		Remarks
9a	Status of submission of Online Monthly and Annual returns	M.R. Submitted till Sept. 2024 within stipulated time A.R. of 2023-24 Submitted on 30-06-2024		NIL
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	None	None	
9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	Covered under current (O-C) Workings - 0.28, Occupied by plant, buildings, residential, welfare buildings and- 0.10, under progressive mine closure plan - 0.90	Covered under current (O-C) Workings -0.28, Occupied by plant, buildings, residential, welfare buildings and-0.10, under progressive mine closure plan - 0.90	
9d	Scrutiny of Annual return on afforestation	150 saplings	150 saplings	
9e	Scrutiny of Annual return on mineral reject generation (Grade & quantity)	Nil	Nil	
9f	Scrutiny of Annual return on ROM stock and/or graded ore	ROM-10MT Cement grade limestone- 50 MT	ROM-10MT Cement grade limestone- 50 MT	
9g	Scrutiny of Annual return on sale value, Ex. Mine price & production cost	EMP - 519.00	EMP - 519.00	
9i	Scrutiny of Annual return on fixed assets	300000	300000	
9k	Scrutiny of Annual return on mining machineries	BACK HOE 1.200 CUM 0	BACK HOE 1.200 CUM 0	

10- Details of violations observed during current inspection and compliance position of earlier violation pointed out: -

- 1. Mining operations are not being carrying out since year 2017-18 due to EC problem.
- 2. No violation pointed out for previous year 2022-23.
- 3. The following rules are found being violated:- 34(A), 45(5)(c) Read with Schedule II. (for not showing Royalty etc for dispatched quantity) Violation-cum show cause for the above said Rules shall be issued.

4. Drone data submitted for the year 2023-24 has been examined and found that it is not as per SOP. Hence referred back in DDMS Portal

Mohammad Nimar DCOM