

INDIAN BUREAU OF MINES
MINERALS DEVELOPMENT AND REGULATION DIVISION
MCDR Inspection REPORT
Jabalpur Regional office

Mine code: 38MPR426007

(i)	Name of Inspecting officer	:	Kathroju Naveen
(ii)	Designation	:	Senior Assistant Controller of Mines
(iii)	Accompanying mine official with Designation	:	Shri Naveen Singh Baghel HOD Mines
(iv)	Date of Inspection	:	24.01.2025
(v)	Previous Inspection date	:	--

PART-I: GENERAL INFORMATION

1	(a)	Mine Name	:	Bela Cement Limestone Mine-01 (415.097 Ha.)
	(b)	Registration Number	:	IBM/441/2011
	(c)	Category	:	Fully Mechanized
	(d)	Type of Working	:	Opencast
	(e)	Postal address		
		State	:	Madhya Pradesh
		District	:	Satna
		Village	:	Devra & Kothar
		Taluka	:	Rampur Baghelan
		Post Office	:	Jaypee Puram
		Pin code	:	486450
		Fax	:	(07662) 409309
		email	:	kishore.moorjani@adityabirla.com
		Phone No	:	9587030510
	(f)	Police Station	:	Chorahata
	(g)	First Opening date	:	01.01.2024
	(h)	Weekly day of rest	:	Sunday
2		Address for Correspondence		UltraTech Cement Limited Unit - Bela Cement Works P.O. - Jaypee Puram, Rewa District - Rewa MP – 486450,
3	(a)	Lease Area	:	415.097 Ha.
	(b)	Period of lease	:	50 Years
	(c)	Date of Expiry	:	04.05.2067
4		Mineral Worked (Main)	:	Limestone
5		Name of address of the Lessee with Phone, email and fax number	:	M/s UltraTech Cement Limited, B wing, Ahura Centre 2nd Floor Mahakhali Caves Road Andheri (East) Mumbai 400 093 Phone - 022 66917800

		Email- kailash.jhanwar@adityabirla.com
	Name of address of the Owner/Nominated Owner with Phone, email, fax number and Date of appointment :	Shri Kailash Chandra Jhanwar B wing, Ahura Centre 2nd Floor, Mahakali Caves Road Andheri (East), Mumbai 400 093 Phone - 022 66917800 Email- kailash.jhanwar@adityabirla.com
	Name of address of the Agent with Phone, email, fax number and Date of appointment :	Shri Kishore Kumar Moorjani Sr. General Manager – Mines & Agent - Mines UltraTech Cement Limited Unit - Bela Cement Works P.O. - Jaypee Puram, Rewa District – Rewa MP – 486450, Mobile No. - 9587030510 Email – kishore.moorjani@adityabirla.com Date of Appointment – 01.01.2024
	Name of address of the Manager with Phone, email, fax number and Date of appointment :	Shri- Milap Mansata UltraTech Cement Limited Unit - Bela Cement Works P.O. - Jaypee Puram, Rewa District - Rewa MP – 486450, Mobile No. - 9166112841 Email-milap.mansata@adityabirla.com Date of Appointment – 12.02.2024
	Mining Engineer Name Qualification Date of Appointment :	Shri- Milap Mansata UltraTech Cement Limited Unit - Bela Cement Works P.O. - Jaypeepuram, Rewa District - Rewa MP – 486450, Mobile No. - 9166112841 Email-milap.mansata@adityabirla.com Date of Appointment – 12.02.2024
	Geologist Name Qualification, Date of Appointment :	Shri Biju Mathew Qualification – M.Sc. & M Tech.Geology Experience – 25 Years UltraTech Cement Limited Unit - Bela Cement Works P.O. - Jaypee Puram, Rewa District - Rewa MP – 486450, Mobile No. - 9819259728 Email – mathew.biju@adityabirla.com Date of Appointment – 01.01.2024
6	Date of approval of Mining Plan/Review of Mining Plan etc. :	Approval Date 15.11.2021, MP/Satna/Limestone/RMP-42/2021-22/6243 (Period 01.04.2022 to 31.03.2027)

PART- II: OBSERVATION/COMMENTS OF INSPECTING OFFICERS**Exploration: (2023-24)**

S.No	Item	Proposals	Actual Work	Remarks
1a	Backlog of previous year	2022-23-30 holes (1500m) 2023-24- 30 holes (1500m)	2022-23 –Nil 2023-24 – 03 holes (200m)	Violation is pointed out under Rule 11(1)
1b	Exploration over lease area for Geological axis 1 or 2	G1	Not explored	
1c	Exploration Agency & Expenditure in Lakh Rupees during the year	Rs 8000000	Pandey Construction Company Rs 550000	
1d	Balance area to be explored to bring the Geological axis in 1 or 2.	G1	G1 102.431 G2 263.447 Unexplored 49.220	
1e	Balance reserves as on 01.04.2024	111 – 7921672 Tons 122 – 34731226 Tons Total- 42652898 Tons		
1f	General remarks of Inspecting officer on geology, exploration etc.	Reserve at the beginning of the plan period category 111- 7921744 Tons 122- 34731226 Tons Depletion in the year 2023-24 - 72 Tons Balance reserve as on 31.03.2024 - 42652898 Tons		

Development (2023-24)

S.N.	Item	Proposals	Actual Work	Remarks
2a	Location of Development w.r.t. lease area	Pit-1 E/W-514130 To 514290.00 N/S- 2710660.00 To 2710940.00	Waste and production have not been achieved as proposed	Violation is pointed out under Rule 11(1).
2b	Separate benches in topsoil overburden and mineral (Rule 15)	Proposed Separate benches	As proposed	
2c	Stripping ratio or ore to OB ratio	01:1.192 (Tons)	01:21.11 (Tons)	Due to very less quantities

2d	Quantity of topsoil generation in m3	30000 M ³	950 M ³	
2e	Quantity of overburden generation in m3	Not Proposed	Nil	
2f	General remarks of Inspecting officer on development of pit w.r.t type of deposit etc.	Waste and production have not been achieved as proposed against which violation is pointed out under Rule 11(1).		

3. Exploitation FY (2023-24)

S. N.	Item	Proposals	Actual Work	Remarks
3a	Number of pits proposed for production	Pit-01	Pit-01	
3b	Quantity of ROM mineral production proposed	250000 Tons	72 Tons	
3c	Recovery of Salable/ usable minerals from ROM production	100%	100%	
3d	Quantity of mineral reject generation	Not proposed	NA	No Mineral Reject
3e	Grade of mineral reject generation and threshold value declared	Not proposed	NA	No Mineral Reject
3f	Quantity of sub-grade mineral generation	Not proposed	NA	No Sub grade Mineral
3g	Grade of sub-grade mineral generation	Not proposed	NA	No Sub grade Mineral
3h	Manual/Mechanized method adopted for segregation from ROM	Fully Mechanised	Fully Mechanised	
3i	Any analysis or beneficiation study proposed & carried out for sub-grade mineral and reject	Not proposed	NA	
3j	Provision of drilling & blasting in mineral benches	Yes	Yes	
3k	Provision of mining machineries in mineral benches	Yes	Yes	

3l	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	Yes		Yes	
3m	Total area covered under excavation /pits (Ha.)	Pit-3.00 Ha		Pit-0.063 Ha	
3n	Ore to OB ratio for the pit/mine during the year	01:1.192 (Tons)		01:21.11 (Tons)	
3o	Total area put in use under different heads at the end of year	Pit-5.25 Ha		Pit-0.17 Ha	
3p	Production of ROM mineral during last five-years period, as Applicable	2019-20 2020-21 2021-22 2022-23 2023-24	500000 750000 1500000 0 250000 Tons	Nil Nil Nil Nil 72 Tons	
3q	General remarks of inspecting officer on method of mining etc.	Production has not been achieved as proposed against which Violation is pointed out under Rule 11(1).			

4. Solid Waste Management-Dumping (2023-24)

S.N .	Item	Proposals	Actual Work	Remarks
4a	Separate dumping of topsoil, OB & mineral reject (Rule 32,33)	Top soil stacking proposed (0.37 Ha.)	0.054 ha	
4b	Location of topsoil, OB & mineral reject dumps	Top Soil Stacking E/W-514265 To 514335 N/S-2711130 To 2711220	Top soil has not generated as proposed	Violation is pointed out under Rule 11(1).
4c	Number of Dumps within lease area and outside lease area	Not Proposed	Nil	

4d	Location of Dumps w.r.t. ultimate pit limit (Rule 16)	Dumps are lying in outside of UPL	Nil	
4e	Number of Active & Alive dumps	Not Proposed	Nil	
4f	Number of dead dumps	NA	NA	
4g	Number of dumps established	Nil	Nil	
4h	Whether Retaining wall or garland drain all along dumps are there	Not Proposed	Nil	
4i	Length of Retaining wall or garland drain all along dump	Not Proposed	Nil	
4j	Number of settling ponds	Not Proposed	Nil	
4k	Specific comments of inspecting officer on waste dump management	Top soil has not been generated as proposed against which Violation is pointed out under Rule 11(1).		

5. Solid Waste Management-Backfilling (2023-24)

S.N.	Item	Proposals	Actual Work	Remarks
5a	Status on part or full extraction of mineral from mined out area before starting backfilling	Not proposed	NA	
5b	Area under backfilling of mined out area	Not Proposed	Nil	
5c	Concurrent use of topsoil for restoration or rehabilitation of mined out area (Rule 32)	30000 M ³	950 M3	Violation is pointed out under Rule 11(1).
5d	Total area fully reclaimed & rehabilitated (Ha)	Not Proposed	Nil	
5e	General remarks of inspecting officer on backfilling, reclamation etc	Top soil has not been achieved as proposed against which the Violation is pointed out under Rule 11(1).		

6. Progressive Mine Closure Plan (2023-24)

S.N.	Item	Proposals	Actual Work	Remarks
6a	Whether Annual report on PMCP submitted on time and correctly-Rule 23E (2). Details should be given in the format as given in Annexure-20	PMCP report to be submitted in time.	PMCP report submitted on time.	
6b	Area available for rehabilitation (Ha)	0.70 Ha	Nil	
6c	Afforestation done (ha)	0.70 Ha	Nil	
6d	No. of saplings planted during the year	1500 Nos	Nil	Violation is pointed out under Rule 11(1).
6e	Cumulative no. of plants	1500 Nos	Nil	
6f	Any other specific method of rehabilitation	Not Proposed	Nil	
6g	Cost incurred on watch & care during the year	Not Proposed	Nil	
6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling (L X B X D).	Not Proposed	Nil	
6i	Compliance on reclamation and rehabilitation by backfilling (ii) Void filled by waste/tailings.	Not Proposed	Nil	
6j	Compliance on reclamation and rehabilitation by backfilling (iii) Afforestation on the backfilled area.	Not Proposed	Nil	
6k	Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir.	Not Proposed	Nil	
6l	Compliance on reclamation and rehabilitation by backfilling (v) Any other specific means	Not Proposed	Nil	
6m	Compliance of Rehabilitation of waste land within lease (i) Afforestation	Not Proposed	Nil	
6n	Compliance of Rehabilitation of waste land within lease (ii) Area rehabilitated (ha) Method of rehabilitation	Not Proposed	Nil	
6o	Compliance of Rehabilitation of waste land within lease (iii) Method of rehabilitation	Not Proposed	Nil	
6p	Compliance of Environment monitoring (core zone & buffer zone)	Monitoring to be done.	Monitoring on monthly basis being carried out.	
6q	General remarks of inspecting officer on PMCP compliance &	Plantation has not been proposed against which the violation is pointed out under Rule 11(1).		

	progressive closer operations	
--	-------------------------------	--

7. Mineral Conservation (2023-24)

S.N.	Item	Proposals	Actual Work	Remarks
7a	ROM mineral dispatch or grade wise sorting within lease area	ROM dispatch proposed.	As per the proposal	
7b	Method of grade-wise mineral sorting i.e. manual or mechanical	Not Proposed	Nil	
7c	Different grade of mineral sort out at mine	Not Proposed	Nil	
7d	Any beneficiation process at mines	Not Proposed	Nil	
7e	General remarks of inspecting officer on Mineral conservation & beneficiation issues			

8. Environment (2023-24)

S. N.	Item	Proposals	Actual Work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	30000 M ³	950 M ³	
8b	Concurrent use or storage of topsoil	Not Proposed	Nil	
8c	Separate dumps for overburden waste rock, rejects and fines (Rule 33)	Not Proposed	Nil	
8d	Use of overburden, waste rock, rejects and fines dump for restoring the land to its original use	Not Proposed	Nil	
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	Not Proposed	Nil	
8f	Baseline information on existence of plantation & additional plantation done (Rule 41)	Total plantation within ML area Nil		
8g	Survival rate	NA	NA	
8h	Water sprinkling on roads to control airborne dust	Dust suppression to be done.	Dust suppression done by using water tankers.	
8i	General remarks of inspecting officer on aesthetic beauty in and around mine area	Violation pointed out under Rule 11(1).		

9. Compliance of Rule 45 (2023-24)

S.N.	Item	Comments			Remarks
9a	Status of submission of monthly and Annual returns	M.R. Submitted up to Dec-2024 dated 09.01.2025. A.R. submitted up to FY 2023-2024 dated 27.06.2024.			
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	Mining Engineer: Milap Masanta Geologist: Dr Biju Mathew			
9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	i. Covered under current (O-C) Workings. 0.063 ha. ii. Occupied by plant, buildings, residential, welfare buildings and roads 0.54 ha. iii. Top Soil Stack 0.053 ha			
9d	Scrutiny of Annual return on afforestation	Nil			Violation pointed out under Rule 11(1).
9e	Scrutiny of Annual return on mineral reject generation (Grade & Quantity)	Nil			
9f	Scrutiny of Annual return on ROM stock and/or grade ore	Not reported			
9g	Scrutiny of Annual return on sale value, Ex. Mine price & production costs	Ex Mine Price Reported 504.19/-			
9i	Scrutiny of Annual return on Fixed assets	Value of Fixed Assets ₹ 2,10,740/-			
9k	Scrutiny of Annual return on mining Machineries	Equipment	Capacity	No of Units	
		Shovel	4.5 Cu.m	01	
		Dumper	55 T	02	
		Dozer	305 HP	01	
		Water Tanker	100000 L	01	

Kathroju Naveen
Senior Assistant Controller of Mines