INDIAN BUREAU OF MINES MINERALS DEVELOPMENT AND REGULATION DIVISION MCDR Inspection REPORT Jabalpur Regional office

Mine code: 38MPR18092

(i)	Name of Inspecting officer		Kathroju Naveen
(ii)	Designation		Senior Assistant Controller of Mines
(iii)	Accompanying mine official with Designation		Mirtyunjoy Prasad Mining Engineer
(iv)	Date of Inspection		28/06/2024
(v)	Previous Inspection date		28/04/2022

PART-I: GENERAL INFORMATION

1	()			Chandan Limestone & Dolomite Mine
1	(a)	Mine Name	:	
	(b)	Registration Number	:	IBM/6898/2011
	(C)	Category	:	A Category
	(d)	Type of Working	:	Mechanized
	(e)	Postal address		M/s Shree Kamal Lime Industries Station Road Katni-483501
		State	:	Madhya Pradesh
		District	:	Katni
		Village	:	Chandan
		Taluka	:	Badwara
		Post Office	:	Raupond
		Pin code	:	483337
		Fax	:	
		email	:	bagaria_group@rediffmail.com
		Phone No	:	+919893158602
	(f)	Police Station	:	Badwara
	(g)	First Opening date	:	07.07.1982
	(h)	Weekly day of rest	:	
2	Add	ress for Correspondence		M/s Shree Kamal Lime Industries Station Road Katni-483501
3		та	:	Total Lease Area-7.205 ha
	(a)	Lease Area		Forest Land-nil Non Forest Land-7.205 ha
	(b)	Period of lease	:	50 Years
	(C)	Date of Expiry	:	06-07-2032
4	Mine	eral Worked (Main)	:	Limestone & Dolomite
		·		Name-M/s Shree Kamal Lime Industries
5		e of address of the Lessee with		Address-Station Road Katni-483501
	Phor	ne, email and fax number	•	Phone: +919893158602
				Email: bagaria_group@rediffmail.com

	Name of address of the		Name- Shree Kishore Kumar
	Owner/Nominated Owner with		Address-Station Road Katni-483501
	Phone, email, fax number and Date	•	Phone: +919893158602
	of appointment		Email: <u>bagaria_group@rediffmail.com</u>
	Name of address of the Agent with		
	Phone, email, fax number and Date	:	-
	of appointment		
	Name of address of the Manager		-
	with Phone, email, fax number and	:	
	Date of appointment		
	Mining Engineer		Name- Miryunjoy Prasad
	Name	:	Qualification-Bachelor
	Qualification		
	Geologist Name		Name-Srinivas Mishra
	Qualification,	:	Qualification- M.Sc
6	Date of approval of Mining		20/06/2022
	Plan/Review of Mining Plan etc.	•	

PART- II: OBSERVATION/COMMENTS OF INSPECTING OFFICERS

S.N	Item	Proposals	Actual Work	Remarks
0				
1a	Backlog of previous year	Not Proposed	N.A.	
1b	Exploration over lease area for Geological axis 1 or 2	G1	G2	
1c	Exploration Agency & Expenditure in Lakh Rupees during the year	Lessee Himself	Lessee Himself	Exploration has not been carried out as proposed violation is pointed out.
1d	Balance area to be explored to bring the Geological axis in 1 or 2.	Nil	G2: 1.745 Non Mineralized 5.4625	
1e	Balance reserves as on 01.04.2024	194612 T	339255 T	
1f	General remarks of Inspecting officer on geology, exploration etc.	litho set up point of view Limestone of band is running in NE- SW to ENE - SWS direction and approx width of band is 60m		d major rocks are l as Dolomite.From d is running in NE- idth of band is 60m Dolomite thus the y associate mineral

Exploration

S.N.	Item	Proposals	Actual Work	Remarks
2a	Location of Development w.r.t. lease area	Proposed to develop at the central part of the pit	As per proposal	
2b	Separate benches in topsoil overburden and mineral (Rule 15)	Nil	Nil	
2c	Stripping ratio or ore to OB ratio	1:0.71	1:0.71	
2d	Quantity of topsoil generation in m3	Nil	Nil	
2e	Quantity of overburden generation in m3	58800	Nil	
2f	General remarks of Inspecting officer on development of pit w.r.t type of deposit etc.			

Development (2023-24)

Exploitation FY 2023-24

S.	Item	Proposals	Actual Work	Remarks
N.				
За	Number of pits proposed for production	One	One	
3b	Quantity of ROM mineral production proposed	ROM-82578Tonne	ROM-11250Tonne	
3с	Recovery of Salable/usable minerals from ROM production	Limestone-64380Tonne Dolomite-18198 tonne	Limestone- 9150Tonne Dolomite-2100 tonne	
3d	Quantity of mineral reject generation	Not Proposed	N.A.	
Зе	Grade of mineral reject generation and threshold value declared	Not Proposed	N.A.	
3f	Quantity of sub- grade mineral generation	Not Proposed	N.A.	

3g	Grade of sub-grade mineral generation	Not I	Proposed	N.A.	
3h	Manual/ Mechanized method adopted for segregation from ROM	Mechanized method		Mechanized method	
3i	Any analysis or beneficiation study proposed & carried out for sub-grade mineral and reject	Not Proposed		N.A.	
Зј	Provision of drilling & blasting in mineral benches	Pro	pposed	Done as per proposal	
3k	Provision of mining machineries in mineral benches	Pro	oposed	Done as per proposal	
31	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	3-4 mt height in ROM		3-4 mt height in ROM	
3m	Total area covered under excavation /pits (Ha.)	2.3765		1.88	
3n	Ore to OB ratio for the pit/mine during the year	1:0.71		1:0.71	
Зо	Total area put in use under different heads at the end of year	4.4635 HA		3.19 HA	
Зр	Production of ROM mineral during last five-years period, as Applicable	2022-23 2023-24	Limestone- 69600Tonne Dolomite- 14755 tonne Limestone- 64380Tonne Dolomite- 18198 tonne	Limestone- 8940Tonne Dolomite-2100 tonne Limestone- 9150Tonne Dolomite-2100 tonne	
Зq	General remarks of inspecting officer on method of mining etc.	the propose	Г of Limestone & d64,380T of lime	2100 T of Dolomite pestone and 18,198 T Dolomite runder Rule 11(1).	

Solid Waste Management-Dumping (FY2023-24)

-

S.N	Item	Proposals	Actual Work	Remarks
• 4a	Separate dumping of topsoil, OB & mineral reject (Rule 32,33)	Not Proposed	N.A.	
4b	Location of topsoil, OB & mineral reject dumps	Not Proposed	N.A.	
4c	Number of Dumps within lease area and outside lease area	Not Proposed	N.A.	
4d	Location of Dumps w.r.t. ultimate pit limit (Rule 16)	Not Proposed	N.A.	
4e	Number of Active & Alive dumps	2 NOS	2 NOS	
4f	Number of dead dumps	Not Proposed	N.A.	
4g	Number of dumps established	Not Proposed	N.A.	
4h	Whether Retaining wall or garland drain all along dumps are there	Garland drain Proposed	Nil	295m of retaining wall and 318m of garland drain proposed during the Reporting year which has not been carried out
4i	Length of Retaining wall or garland drain all along dump	Garland drain-295 MT	Nil	
4j	Number of settling ponds	Not Proposed	N.A.	
4k	Specific comments of inspecting officer on waste dump management	295m of retaining wall and 318m of garland drain proposed during the Reporting year which has not been carried out for which the violation is pointed out under Rule 11(1).		

S.N	Item	Proposals	Actual Work	Remarks
• 5a	Status on part or full extraction of mineral from mined out area before starting backfilling	Nil	Nil	
5b	Area under backfilling of mined out area	Not Proposed	N.A.	
5c	Concurrent use of topsoil for restoration or rehabilitation of mined out area (Rule 32)	Not Proposed	N.A.	
5d	Total area fully reclaimed & rehabilitated (Ha)	Not Proposed	N.A.	
5e	General remarks of inspecting officer on backfilling, reclamation etc	Back filling not proposed for the Reporting Year		

Solid Waste Management-Backfilling (FY 2023-24)

Progressive Mine Closure Plan (FY 2023-24)

S.N	Item	Proposals	Actual Work	Remarks
6a	Whether Annual report on PMCP submitted on time and correctly-Rule 23E (2). Details should be given in the format as given in Annexure-20	Proposed	Yes	
6b	Area available for rehabilitation (Ha)	Not Proposed	N.A.	
6c	Afforestation done (ha)	0.27	0.25	
6d	No. of saplings planted during the year	300	Nil	Plantation has not been carried out as proposed
6e	Cumulative no. of plants	600	NA	
6f	Any other specific method of rehabilitation	Not Proposed	N.A.	

6g	Cost incurred on watch &	20000	15000	
~8	care during the year			
	Compliance on reclamation	Not Proposed	N.A.	
	and rehabilitation by			
6h	backfilling			
	(i)Voids available for			
	backfilling (L X B X D). Compliance on reclamation	Not Proposed	N.A.	
	and rehabilitation by	Not Proposed	N.A.	
6i	backfilling			
	(ii) Void filled by			
	waste/tailings.			
	Compliance on reclamation	Not Proposed	N.A.	
	and rehabilitation by	L		
6j	backfilling			
5	(iii) Afforestation on the			
	backfilled area.			
	Compliance on reclamation	Not Proposed	N.A.	
	and rehabilitation by			
6k	backfilling			
	(iv) Rehabilitation by			
	making water reservoir.		DT A	
	Compliance on reclamation	Not Proposed	N.A.	
61	and rehabilitation by backfilling			
	(v) Any other specific means			
	Compliance of	Not Proposed	N.A.	
6	Rehabilitation of waste land	riot roposed	1 (11 1)	
m	within lease			
	(i)Afforestation			
	Compliance of	Not Proposed	N.A.	
	Rehabilitation of waste land			
6n	within lease			
	(ii) Area rehabilitated (ha)			
	Method of rehabilitation			
	Compliance of	Not Proposed	N.A.	
60	Rehabilitation of waste land			
	within lease			
	(iii) Method of rehabilitation	Proposed	Done	
60	Compliance of Environment monitoring (core zone &	rioposeu	DOILG	
6р	buffer zone)			
	General remarks of			
	inspecting officer on PMCP	Plantation has not be	een carried out as pro	oposed
6q	compliance & progressive		-	-
compliance & progressive violation is pointed out under closer operations			,	

Mineral Conservation (FY 2023-24)

S.N Item Prop	sals Actual Remarks
---------------	---------------------

•			Work	
7a	ROM mineral dispatch or grade	ROM dispatch	ROM dispatch	
/ d	wise sorting within lease area			
	Method of grade-wise mineral	Manual	Manual	
7b	sorting			
	i.e. manual or mechanical			
7c	Different grade of mineral sort	Not Proposed	N.A.	
	out at mine			
7d	Any beneficiation process at	Not Proposed	N.A.	
/u	mines			
	General remarks of inspecting	NO grade wise sorting observed Produced ROM is being dispatched.		
7e	officer on Mineral conservation			
	& beneficiation issues			

Environment (FY 2023-24)

S. N.	Item	Proposals	Actual Work Remark	s
8a	Separate removal and utilization of topsoil (Rule32)	Not Proposed	N.A.	
8b	Concurrent use or storage of topsoil	Not Proposed	N.A.	
8c	Separate dumps for overburden waste rock, rejects and fines (Rule 33)	Not Proposed	N.A.	
8d	Use of overburden, waste rock, rejects and fines dump for restoring the land to its original use	Not Proposed	N.A.	
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	Not Proposed	N.A.	
8f	Baseline information on existence of plantation & additional plantation done (Rule 41)	By Green belt 300 nos of plan	Nil	
8g	Survival rate	80%	80%	
8h	Water sprinkling on roads to control airborne dust	Proposed	Maintained as per proposal	
8i	General remarks of inspecting officer on aesthetic beauty in and around mine area	Plantation has not been carried out as proposed violation is pointed out under Rule 11(1).		

S.N	Item	Comments		Remarks	
•					
9a	Status of submission of monthly and Annual returns	Submitted			
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	Yes			
9с	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	Yes			
9d	Scrutiny of Annual return on afforestation	Reported 300 saplings			Violation pointed out under Rule 11(1)
9e	Scrutiny of Annual return on mineral reject generation (Grade & Quantity)	Nil			
9f	Scrutiny of Annual return on ROM stock and/or grade ore	594.371 T stock reported.			
9g	Scrutiny of Annual return on sale value, Ex. Mine price & production costs	Ex Mine price Reported 320.00/- Sale Value reported 320.00/-			
9i	Scrutiny of Annual return on Fixed assets	Value of Fixed Assets ₹ 5146192/-			
9k	Scrutiny of Annual return	Equipment	Capacity	No of Units	
JK	on mining Machineries	Water tanker	5000 Ltr	01	

Compliance of Rule 45 (2023-24)

S.No	Violation Under Rule	Issued on	Compliance Received	SCN Issued on	Compliance Received
01	11(1)	20/08/2024	04/11/2024	08/11/2024	14/12/2024
02	31(4)	20/08/2024	04/11/2024	08/11/2024	14/12/2024
03	34(A)	20/08/2024	04/11/2024	08/11/2024	14/12/2024

04 45(7) 20/08/2024	04/11/2024	08/11/2024	14/12/2024
---------------------	------------	------------	------------

Kathroju Naveen Senior Assistant Controller of Mines