



भारत सरकार/Government of India
खान मंत्रालय/Ministry of Mines
भारतीय खान ब्यूरो/Indian Bureau of Mines
क्षेत्रीय खान नियंत्रक, गोवा का कार्यालय/Office of the RCOM, Goa



Phone No.: (0832)-2741757
Fax No. : (0832)-2741758
E-mail : ro.goa@ibm.gov.in

Opp. R.T.O. Office,
P.O. FATORDA – 403 602
MARGAO - GOA

No.: MCDR-MiFLOLST/5/2022-GOA-IBM_RO_GOA

Mine Code: 38KAR02038

सेवा में/ To,

The Nominated Owner

Yadwad & Kunnal Limestone Mine (ML No. 0002)

M/s. Dalmia Cement (Bharat) Ltd.

Village: Yadwad, Taluk: Mudalagi

District: Belagavi, Karnataka: 591 136

Mail ID: v.karthikeyan@dalmiacement.com; kawale.anildadaji@dalmiacement.com

Subject: Violation of provisions of Mineral Conservation and Development Rules, 2017 (MCDR'2017) in respect of your Yadwad & Kunnal Limestone Mine, ML No. 002, Extent 1048.24 Ha., situated in Gokak and Ramdurg Taluks, Belagavi District of Karnataka State.

महोदय/Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during the inspection on 16th April 2024 by the undersigned in the presence of Shri Anil D. Kawale (Mines Head) & Shri Anil Gupta (Mines Manager/Mining Engineer) and other mining officials:

Rules	Nature of Violations observed
11 (1)	<p>The mining operation in the lease hold area is not carried out as per the approved Review of Mining Plan dated 10.11.2020 to the extent mentioned below:</p> <ol style="list-style-type: none"> Mine working at the South Eastern side of Pit was not found to be carried out as per the approved document Blasted material with poor fragmentation and excessive boulders were observed during the inspection in the pit bottom area. Settling Tank has not been constructed as per the approved document.

02. It is brought to your notice that violation of the above Rules constitutes an offence punishable under Rule 62 (1) of MCDR (Amendment) 2021, notified dated 03.11.2021.

03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

1/30938/2024. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

Sr. Asst. Controller of Mines
Indian Bureau of Mines

Copy for kind information to (by mail):

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

Sr. Asst. Controller of Mines
Indian Bureau of Mines