

INDIAN BUREAU OF MINES

--:-- Inspection Report --:--

Part-I : General Information

1.1.1 Mine Details

Name of the Mine :	38HPR10010	Lease Area (Ha) :	4.444
Forest Area (Ha) :	N/A	Mine Code :	38HPR10010
Registration Number :	IBM/12351/2012	Name of lessee :	MRIGENDRA
Address of lessee :	M/S DURGA LIME STONE MINE ,VILLAGE BORLI, TEHSIL SANGRAH	Phone of lessee :	-
Email of lessee :	Hemangsinghbhatee@gmail.com	Fax Number :	N/A
Village :	Borli (113)	Taluka / Mandal :	Renuka
District :	Sirmaur	Pincode :	173023
State :	Himachal Pradesh	Post Office :	N/A
Nearest Police Station :	N/A	Nearest Railway Station :	N/A
Date of Grant of Mining Lease :	1984-04-30	Date of Mining Lease Execution :	1984-04-20
Date of opening in the mine :	Nilsss		

Nominated Owner Details			
Name of the Nominated Owner :	N/A	Nominated Owner Address:	N/A
Nominated Owner Mobile :	N/A	Nominated Owner Email :	N/A
Nominated Owner Fax Number :	Nil	Date of Nominated Owner Appointment :	Nil
Mining Engineer Details			
Name of the Mining Engineer :	Shri Ravindar Yadav	Qualification of Mining Engineer :	Bachelor In Technology
Address of Mining Engineer :	Village & Post- Satun, Tehsil- Paonta Sahib District – Sirmour (H.P)-173022	Phone of Mining Engineer :	9816768232
Email of Mining Engineer :	Guptaassociates009@gmail.com	Fax Number of Mining Engineer :	N/A
Date of Mining Engineer Appointment :	2025-04-01		
Geologist Details			
Name of the Geologist :	Shri Lala Sanjeev Prasad	Qualification of Geologist :	Msc
Address of Geologist :	Village & Post- Satun, Tehsil- Paonta Sahib District – Sirmour (H.P)-173022	Phone of Geologist :	9816768232
Email of Geologist :	Guptaassociates009@gmail.com	Fax Number of Geologist :	N/A
Date of Geologist Appointment :	2025-04-01		
Mine Manager Details			
Name of the Mine Manager :	Shri Ravindar Yadav	Qualification of Mine Manager :	Bachelor In Technology
Address of Mine Manger :	Village & Post- Satun, Tehsil- Paonta Sahib District – Sirmour (H.P)-173022	Phone of Mine Manger :	9816768232

Email of Mine Manger :	Guptaassociates009@gmail.com	Fax Number of Mine Manger :	N/A
Date of Mine Manger Appointment :	2025-04-01		
Mineral(s) granted in lease and proved for mining :	LIMESTONE	Date of Approval of Mining Plan / Modified Mining Plan / ROMP with five-year period :	N/A
Method of mining :	Open Cast	Category :	OTHER_THAN_MECHANISED
Nature of Use :	Non Captive		

Part-II : Other Information

2.1.1 : Inspection Details

Inspecting Officer :	NITIN SINGH
Designation :	JMG
Name of the Accompanying Official from Mine :	Shri Ravinder Yadav
Designation of the Accompanying Official :	Mines Manager
Type of Inspection :	MCDR,MPAS,STR
Date of Inspection :	16/10/2025
Review year considered for MCDR Inspection :	2024-2025

Final Submitted

2.2.1 : Exploration Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Number of Core Boreholes	No borehole proposed	Not done by the lessee	No	No Violation	1) 1 core borehole has been done in 2022-23 as per the proposals. 2) 2 core boreholes have been done in 2023-24 as per the proposals.	Nil
2	Number of DTH Boreholes	No DTH borehole proposed	Not done by the lessee	No	No Violation	Nil	Nil
3	Number of exploratory pits / trial pits	Not proposed	Not applicable	No	No Violation	Nil	Nil
4	Number of exploratory Trenches	Not proposed	Not applicable	No	No Violation	Nil	Nil
5	Lateral exploration status for the lease area	G1	1.531 Ha	1.531 Ha	Nil	No Violation	Nil
6		G2	0.90 Ha	0.90 Ha	Nil	No Violation	Nil
7		G3	2.012 Ha	2.012 Ha	Nil	No Violation	Nil
8		G4	0	0	0.000	No Violation	Nil
9	UNFC category wise reported Resources/Reserves as per MP/MMP	Total Reserves as on 01.04.2025	Total Reserves as on 01.04.2025	0.000	Rule 11(1)	0 T production done during	Nil

	ROMP Total Reserves (111, 121 & 122) and Total Mineral Resources (331, 332 & 333 upto 334)	111-657828 T 121-0 122-372140 T Total Resources 211- 373148 T 222-500829 T 331-0 332-0 333-6050124 T	111-774068 T 121-0 122-372140 T Total Resources 211- 373148 T 222-500829 T 331-0 332-0 333-6050124 T			2024-25. violation has been pointed out for why the production has not been done.	
--	---	---	---	--	--	--	--

2.3.1 : Development - Opencast Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Location of development w.r.t. lease area	Developments of 3 benches have been proposed in 3 pits. pit1- Bench Level 1875-1870 mRL pit2-Bench Level 1790-1785 mRL pit3-1690-1685 mRL	developments of benches have not been done	yes	Rule 11(1)	0 T production has been done.	Nil
2	Quantity of overburden generation in m3	780 m3 quantity of waste proposed	0 m3 waste generated during the reporting year	yes	No Violation	Production has not been done during the reporting year.	Nil
3	Quantity of topsoil generation in m3	Not proposed	Not applicable	No	No Violation	topsoil generation has not been proposed for the	Nil

						reporting year.	
4	Stripping ratio : ore to OB ratio	1:05	0	0	No Violation	Production of ROM has not been done during the reporting year.	Nil

2.4.1 Exploitation - Opencast Mine Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Number of pits / Blocks proposed for production	Production proposed in 3 pits, pit1, pit2 and pit3.	production has not been done during the reporting year.	yes	No Violation	violation has been pointed out for the same earlier.	Nil
2	Quantity of ROM mineral production proposed (in T)	37050 T	0	yes	Rule 11(1)	violation has been pointed out.	Nil
3	Recovery of salable/usable mineral quantity from ROM production in T)	95 %	0	0	No Violation	production has not been done during the reporting year. violation has been pointed out for the same earlier.	Nil
4	Quantity of mineral reject/Sub-grade generation	Not proposed	not applicable	0	No Violation	Nil	Nil

5	Grade of mineral reject/sub-grade generation as per threshold value declared	Not proposed	not applicable	0	No Violation	Nil	Nil
6	Manual/Mechanised method adopted for segregating subgrade/mineral rejects from ROM	Not proposed	not applicable	0	No Violation	Nil	Nil
7	Whether height of benches in Overburden& mineral suitable for method of mining proposed in mining plan	Formation of benches with 5 m height have been proposed.	developments of benches has not been done	yes	No Violation	production has not been done during the reporting year. violation has been pointed out for the same earlier.	Nil
8	Any analysis or beneficiation study proposed & carried out for sub-grade mineral and reject	Not proposed	not applicable	0	No Violation	Nil	Nil

Final Submitted

2.4.3 : Exploitation - Dump Working Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Number of dumps proposed for production	Not proposed	Not applicable	No	No Violation	Nil	Nil
2	Quantity of dump material handling Proposed (in Tonne)	Not proposed	Not applicable	No	No Violation	Nil	Nil
3	Recovery of salable/usable mineral from dump production (in Tonne)	Not proposed	Not applicable	No	No Violation	Nil	Nil
4	Production from dump(s) during the year	Not proposed	Not applicable	No	No Violation	Nil	Nil
5	Quantity of mineral reject generation	Not proposed	Not applicable	No	No Violation	Nil	Nil
6	Grade of mineral reject generation and threshold value declared	Not proposed	Not applicable	No	No Violation	Nil	Nil
7	Any analysis or beneficiation study proposed & carried out for mineral reject	Not proposed	Not applicable	No	No Violation	Nil	Nil
8	Manual / Mechanized method adopted for dump working	Not proposed	Not applicable	No	No Violation	Nil	Nil

Final Submitted

2.5.1 : OB/Waste Dumps Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Separate dumping of topsoil, OB & mineral rejects, fines, tailings (Rule 36,37)	Dumping of waste proposed in 3 dumps, D1, D2 and D3	0 T waste generated during the reporting year	0	No Violation	Nil	Nil
2	Location of Topsoil, OB/Waste, Mineral Reject dumps, Tailings and Fines	D1- 14 91 N to 1524 N, 19 32 E to 19 83 E D2- 14 98 to 15 21 N, 18 92 to 1925 E D3- 15 91 to 16 21 N, 14 82 to 15 25 E	0 T waste generated during the reporting year	0	No Violation	Nil	Nil
3	Number of active & Inative dumps	Active dumps- D1, D2 Inactive dump- D3	as per proposals	0	No Violation	Nil	Nil
4	Number of dead dumps	0	0	0.000	No Violation	Nil	Nil
5	Number of dumps proposed for stabilished	0	0	0.000	No Violation	Nil	Nil
6	Stabilization Technique (Terracing, plantation, geo-textiles etc.)	Not Proposed	Not applicable	0	No Violation	Nil	Nil

Final Submitted

2.6.1 : Solid Waste Management - Backfilling (Opencast) Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Status on part or full extraction of mineral from mined out area before starting backfilling	Not proposed	Not applicable	0	No Violation	Nil	Nil
2	Year-wise area under backfilling of mined out area	Not proposed	Not applicable	0	No Violation	Nil	Nil
3	Year-wise topsoil generation, Utilization and Stored proposal (in m3)	Not proposed	Not applicable	0	No Violation	Nil	Nil
4	Total area fully reclaimed & rehabilitated	Not proposed	Not applicable	0	No Violation	Nil	Nil
5	Locations of proposed reclamation & rehabilitated	Not proposed	Not applicable	0	No Violation	Nil	Nil

Final Submitted

2.7.1 : Progressive Mine Closure Plan (PMCP) Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Compliance on reclamation and rehabilitation by backfilling/Other means Total area and numbers of plantation proposed.	Plantation over worked out mines have been proposed over an area of 0.03 Ha with 30 numbers of saplings.	as per proposals	0	No Violation	Nil	Nil
2	Rehabilitation by making water reservoir	Not Proposed	Not applicable	0	No Violation	Nil	Nil
3	Compliance of Rehabilitation of waste land within lease i) Afforestation ii) Area rehabilitated (ha) iii) Method of rehabilitation	95 plantation have been proposed over an area of 0.05 Ha in 7.5m safety barrier zone.	Broadly as per the proposal.	0	No Violation	Nil	Nil
4	Compliance of Environmental monitoring (core zone & buffer zone)	proposed	done as per the proposals	0	No Violation	Nil	Nil

Final Submitted

2.8.1 : Mineral Conservation Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	ROM Mineral dispatch or grade-wise sorting within lease area	ROM Mineral dispatch proposed from the mine head.	0 T production has been done during the reporting year.	0	No Violation	violation has been pointed out earlier.	Nil
2	Different grade of mineral sorted out at mines	Not proposed	Not applicable	0	No Violation	Nil	Nil
3	Any beneficiation process at mines	Not proposed	Not applicable	0	No Violation	Nil	Nil
5	Utilization of Mineral Rejects or Sub-grade (Blending at ROM stage, Blending after Processing etc.)	Not proposed	Not applicable	0	No Violation	Nil	Nil

Final Submitted

2.9.1 : Environment Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Separate removal and utilization of topsoil	Not proposed	Not applicable	No	No Violation	Nil	Nil
2	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	Not proposed	Not applicable	No	No Violation	Nil	Nil
3	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	plantation/regression of the benches proposed over an area of 0.044 Ha	as per proposal	No	No Violation	Nil	Nil
4	Plantation & Survival rate	Total 135 no of plantations have been proposed	as per proposal	No	No Violation	Nil	Nil
5	Water sprinkling on roads to control airborne dust	Water sprinkling on roads to control airborne dust proposed	Water sprinkling has been done by water tankers.	No	No Violation	Nil	Nil

2.10 : Annual Return Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
------	---------------------	-----------------------------	--------	-----------	----------------------	--------	-------------

1	Submission of Online Monthly and Annual returns in prescribed period or not	proposals have been given for timely submission.	Monthly and Annual returns submitted timely online	No	No Violation		Nil
2	Appointment of Mining Engineer & Geologist as per provisions of Rule 55 of MCDR,2017	proposals have been given for appointment of Mining Engineer & Geologist as per provisions of Rule 55 of MCDR,2017	Mining Engineer & Geologist appointed in the mine as per provisions of Rule 55 of MCDR,2017	No	No Violation	Mining Engineer- Shri Ravi Bhushan Singh, Geologist- Shri LSK Prasad	Nil
3	Whether incomplete or false or wrong returns submitted (Rule 45(7))	proposals have been given for not submitting incomplete or false or wrong information in the returns	Not as per proposals	Yes	Rule 45(7)	2 boreholes done during the reporting year but in the annual return mentioned as 4 boreholes which needs to be corrected.	Nil
4	Status of Approval of FMPCP u/r 24, 25 of MCDR,2017	Not Proposed	Not applicable	No	No Violation	Nil	Nil
5	Notices and Returns for the lease area submitted or not where fine applicable	proposals have been given for the submission of the Notices and Returns for the lease area	As per proposals	No	No Violation	Nil	Nil
6	Scrutiny of Annual return on sale value, Ex. Mine price & production cost	proposals have been given for Scrutiny of Annual return on sale value, Ex. Mine price & production cost	Production during the reporting year has not been done.	No	No Violation	Nil	Nil

2.11 : SDF Details

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Start Ratings accorded for mine during last 3 years	self assessment of star ratings submitted for 3 star	Star rating for the year 2023-24- 3 star. Star rating for the year 2024-25 yet to be validated	No	No Violation	Nil	Nil

Part-III : Other Reports**3.1.1 : Upload Other Reports**

S.N.	Reports File	Remark File Description
1	Nil	No other report

Part-IV : Summary Details

4.1 : Summary of Violations

S.N.	Items for Reporting	As Per Approved Mining Plan	Actual	Deviation	Violation under Rule	Remark	Remark File
1	Exploration : UNFC category wise reported Resources/Reserves as per MP/MMP ROMP Total Reserves (111, 121 & 122) and Total Mineral Resources (331, 332 & 333 upto 334)	Total Reserves as on 01.04.2025 111-657828 T 121-0 122-372140 T Total Resources 211- 373148 T 222-500829 T 331-0 332-0 333-6050124 T	Total Reserves as on 01.04.2025 111-774068 T 121-0 122-372140 T Total Resources 211- 373148 T 222-500829 T 331-0 332-0 333-6050124 T	0.000	Rule 11(1)	0 T production done during 2024-25. violation has been pointed out for why the production has not been done.	Nil
2	Development - Opencast : Location of development w.r.t. lease area	Developments of 3 benches have been proposed in 3 pits. pit1- Bench Level 1875-1870 mRL pit2-Bench Level 1790-1785 mRL pit3-1690-1685 mRL	developments of benches have not been done	yes	Rule 11(1)	0 T production has been done.	Nil
3	Exploitation - Opencast Mine : Quantity of ROM mineral production proposed (in T)	37050 T	0	yes	Rule 11(1)	violation has been pointed out.	Nil
4	Annual Return : Whether incomplete or false or wrong returns submitted (Rule 45(7))	proposals have been given for not submitting	Not as per proposals	Yes	Rule 45(7)	2 boreholes done during the reporting year but	Nil

		incomplete or false or wrong information in the returns				in the annual return mentioned as 4 boreholes which needs to be corrected.	
--	--	---	--	--	--	--	--

Final Submitted

Esigned by:  SINGH
Date: 17/11/2025 02:29:56 PM